

**PORT OF TACOMA  
TACOMA, WASHINGTON  
W. SITCUM BLDGS. 900, 700, 975, 575 AND 75 ROOF  
REPLACEMENTS**

**PROJECT NO. 201062.04  
CONTRACT NO. 071126**

**Appendices A Part 1**

**Trevor Thornsley, P.E.  
Director, Engineering**

**Elly Bulega, P.E.  
Project Manager**

**END OF PROJECT TITLE PAGE**

## **PROCUREMENT AND CONTRACTING REQUIREMENTS**

### DIVISION 00 -- PROCUREMENT AND CONTRACTING REQUIREMENTS

- 00 01 01 - Project Title Page
- 00 01 07 - Seals Page
- 00 01 10 - Table of Contents
- 00 01 15 - List of Drawing Sheets
- 00 11 13 - Advertisement for Bids
- 00 21 00 - Instructions to Bidders
- 00 26 00 - Substitution Procedures
- 00 31 00 - Available Project Information
- 00 31 26 - Existing Hazardous Material Information
- 00 41 00 - Bid Form
- 00 43 13 - Bid Security Form
- 00 45 13 - Responsibility Detail Form
- 00 52 00 - Agreement Form
- 00 61 13.13 - Performance Bond
- 00 61 13.16 - Payment Bond
- 00 61 23 - Retainage Bond
- 00 61 23.13 - Retainage Escrow Agreement
- 00 72 00 - General Conditions
- 00 73 16 - Insurance Requirements
- 00 73 46 - Washington State Prevailing Wage Rates
- 00 73 63 - Security Requirements

## **SPECIFICATIONS**

### DIVISION 01 -- GENERAL REQUIREMENTS

- 01 10 00 - Summary
- 01 14 00 - Work Restrictions
- 01 20 00 - Price and Payment Procedures
- 01 26 00 - Change Management Procedures
- 01 29 73 - Schedule of Values
- 01 30 00 - Administrative Requirements
- 01 31 23 - Web-based Construction Management
- 01 32 16 - Construction Progress Schedule
- 01 33 00 - Submittal Procedures

DIVISION 00 - PROCUREMENT AND CONTRACTING REQUIREMENTS  
SECTION 00 01 10 - TABLE OF CONTENTS

---

01 35 29 - Health, Safety, and Emergency Response Procedures

01 35 43.13 - Hazardous Materials Handling Procedure

01 35 47 - Air and Noise Control Procedures

01 41 00 - Regulatory Requirements

01 42 19 - Reference Standards

01 45 00 - Quality Control

01 50 00 - Temporary Facilities and Controls

01 55 00 - Vehicular Access and Parking

01 57 13 - TESC and Project SWPPP

01 60 00 - Product Requirements

01 70 00 - Execution and Closeout Requirements

01 71 00 - Examination and Preparation

01 74 13 - Construction Cleaning

DIVISION 02 -- EXISTING CONDITIONS

02 41 00 - Demolition

02 82 13 - Asbestos Abatement

DIVISION 05 -- METALS

05 50 00 - Metal Fabrications

05 53 05 - Gratings and Floor Plates

DIVISION 06 -- WOOD, PLASTICS, AND COMPOSITES

06 10 00 - Rough Carpentry

06 18 00 - Glued-Laminated Construction

DIVISION 07 -- THERMAL AND MOISTURE PROTECTION

07 01 50.19 - Preparation for Re-Roofing

07 18 00 - Traffic Coatings

07 21 00 - Thermal Insulation

07 54 23 - Thermoplastic Polyolefin (TPO) Membrane Roofing

07 62 00 - Sheet Metal Flashing and Trim

DIVISION 09 -- FINISHES

09 90 00 - Painting and Coating

DIVISION 10 -- SPECIALTIES

10 81 13 - Bird Control Devices

DIVISION 26 -- ELECTRICAL

26 00 00 - Electrical General Conditions

**APPENDIX A**

**HAZARDOUS BUILDING**

**MATERIALS INVESTIGATION**

**REPORT**

October 23, 2018

Mr. Lee Davenport  
Helix Design Group, Inc.  
6021 12<sup>th</sup> Street East, Suite 201  
Tacoma, Washington 98424

Subject: Port of Tacoma 8-Building Roof Replacement  
Building 700 Domestic Equipment Control Building  
Hazardous Building Materials Investigation  
Tacoma, Washington  
Med-Tox Northwest Project No. A-8772.4

Dear Lee;

Shaun Childress of Med-Tox Northwest performed a limited asbestos and hazardous building materials (HBM) survey of Port of Tacoma Building 700 Domestic Equipment Control building located at the end of 14 East 11<sup>th</sup> Street at the Port of Tacoma in Tacoma, Washington. The investigation was performed on September 17, 2018 and was limited to the roof system and roof top mechanical systems.

The purpose of the investigation was to assist the Port of Tacoma with communicating the presence and location of asbestos-containing materials (ACM) and potential lead hazards to employees and contractors working on the roof replacement project. It was also performed to meet the requirements for an asbestos survey by Puget Sound Clean Air Agency (PSCAA) and a good faith inspection as required by Washington State Department of Labor and Industries' Division of Occupational Safety and Health (DOSH) regulation Washington Administrative Code (WAC) 296-62-077 prior to renovation.

As required by WAC 296-62-077 and PSCAA Regulation III, Article 4, an Asbestos Hazard Emergency Response Act (AHERA) accredited building inspector performed the survey. A copy of the building inspector certificate is attached to this letter report.

## **BUILDING INFORMATION**

Building 700 is a three-story structure with approximately 5,060 square feet. Roof access is available via a building access ladder and stairwell. The roof system is a built-up roof with 5 to 6-inches of foam insulation which is applied on a wood roof substrate. Renovations will include demolition of the existing roof system and demolition of roof top heating, ventilation and air conditioning (HVAC) systems.

## ASBESTOS SURVEY

In total, 9 samples were collected of suspect asbestos-containing materials. Of the 9 samples collected, all were determined to be negative for asbestos by Polarized Light Microscopy (PLM) analysis. For a complete list of all materials sampled, please refer to the Summary of Materials Sampled for Asbestos attached to the laboratory report.

**Table 1** summarizes ACM identified by homogeneous material (HM) surveyed by MTNW. Friability was determined by conditions observed during the survey and by how the material behaves during mechanical demolition.

**Table 1. Summary of Asbestos-Containing Materials**

Material	Location	Friable	Quantity
There were no asbestos-containing materials identified.			

Note: This table is not to be used without the complete survey document including appendices for additional information.

Bulk samples were analyzed by Polarized Light Microscopy (PLM) dispersion staining EPA Method 600/R-93/116 by Seattle Asbestos Test, Inc. (SAT). SAT is accredited through the National Voluntary Laboratory Accreditation Program (NVLAP) of the U. S. Department of Commerce. This accreditation does not constitute endorsement, but rather a finding of laboratory competence (certification copy is attached).

## LEAD ASSESSMENT

HVAC units on the roof have factory applied coating on recyclable metal components; these coatings are assumed to contain lead and heavy metal content. Factory coated metal roof flashing or other metal building components are also assumed to contain lead and heavy metal content.

## **SUMMARY/CONCLUSION**

There were no asbestos-containing materials identified in the roofing samples collected from building 700.

MTNW recommends that this survey report be placed on-site during renovation and/or demolition and copies provided to the contractor(s) bidding and performing work. WISHA, OSHA and PSCAA require that the report be on-site and available for review during the entire project duration.

WAC 296-155-176, the Lead in Construction standard, has not defined a minimum concentration for regulating lead and has clarified that lead at any detectable concentration shall be considered regulated (WAC 296-155-176, Lead). Med-Tox Northwest recommends the contractor performing demolition of the HVAC units provide a written lead compliance plan and implement the requirements of WAC 296-155-176 for any work disturbing painted surfaces.

If you have any questions or need additional information, please contact me at (253) 351-0677.


Sincerely,

Anthony Fullerton  
Project Manager

Attachments



Photograph 1: Building 700.



Photograph 2: Built-up roof system. All suspect materials were determined to be negative for asbestos.

# Certificate of Completion

This is to certify that  
**Shaun Z. Childress**  
has satisfactorily completed  
4 hours of refresher training as an  
**AHERA Building Inspector**

to comply with the training requirements of  
**TSCA Title II, 40 CFR 763 (AHERA)**

163731  
Certificate Number



Oct 18, 2017

Expires in 1 year.

Date(s) of Training

Exam Score: N/A  
If appropriate:

*Mary Czajka*

Instructor

### Summary of Materials Sampled for Asbestos

Sample	Material	Location	AHERA Type	HM	Result
8772.4-SC-700-093	Built up	Upper roof, South wall, center	Miscellaneous	1	ND
8772.4-SC-700-094	Built up	Upper roof, North wall, center	Miscellaneous	1	ND
8772.4-SC-700-095	Built Up	Upper roof, West wall, center	Miscellaneous	1	ND
8772.4-SC-700-096	Torch down	Lower roof, center	Miscellaneous	2	ND
8772.4-SC-700-097	Torch down	Lower roof, Northeast corner	Miscellaneous	2	ND
8772.4-SC-700-098	Torch down	Lower roof, Southeast corner	Miscellaneous	2	ND
8772.4-SC-700-099	Gray seam sealant	Lower roof, East wall, center	Miscellaneous	3	ND
8772.4-SC-700-100	Gray seam sealant	Upper roof, Northeast corner	Miscellaneous	3	ND
8772.4-SC-700-101	Gray seam sealant	Upper roof, Southeast corner	Miscellaneous	3	ND

HM = homogeneous material, ND = none detected.

United States Department of Commerce  
National Institute of Standards and Technology



---

## Certificate of Accreditation to ISO/IEC 17025:2005

---

NVLAP LAB CODE: 200768-0

**Seattle Asbestos Test, LLC**  
Lynnwood, WA

*is accredited by the National Voluntary Laboratory Accreditation Program for specific services,  
listed on the Scope of Accreditation, for:*

### **Asbestos Fiber Analysis**

*This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005.  
This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality  
management system (refer to joint ISO-ILAC-IAF Communiqué dated January 2009).*

---

2018-10-01 through 2019-09-30

Effective Dates



  
For the National Voluntary Laboratory Accreditation Program

SEATTLE ASBESTOS TEST, LLC  
19711 Scriber Lake Rd. Suite D, Lynnwood, WA 98036  
Tel: (425) 673-9850, Fax: (425) 673-9810 Website: seattleasbestostest.com

BATCH # 201812763

### CHAIN OF CUSTODY

Analysis Type: Bulk Analysis X Point Count 400 \_\_\_\_\_ Point Count 1000 \_\_\_\_\_ Point Count Gravimetric \_\_\_\_\_

Turn Around Time STD Number of Samples 9 Client Job # 8772.4

Client Name Med-Tox Northwest


Address Post Office Box 1446 City Auburn State WA Zip 98071-1446

Phone 253-351-0677 Fax 253-351-0688 Email havelockj@medtoxnw.com & childresss@medtoxnw.com

Project Location: Port of Tacoma - building 700 Project Manager: Jon Havelock

Sample Condition: Good \_\_\_\_\_ Damaged \_\_\_\_\_ Severe Damage (Spillage) \_\_\_\_\_

SEQ#	SAMPLE ID	SAMPLE DESCRIPTION	Lab ID	Comment	A/R
1					
2		<i>See attached data sheet</i>			
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					

	Print	Signature	Company Name	Date	Time
Sampled by	Shaun Childress		Med-Tox Northwest	<u>9/19/18</u>	<u>16:00</u>
Relinquished by	Shaun Childress		Med-Tox Northwest	<u>9/19/18</u>	<u>16:00</u>
Delivered by	FedEx				
Received by	<i>Betsy Song</i>		SAT	<u>9/20/18</u>	<u>10:10</u>
Analyzed by	<i>Eric Teng</i>		SAT	<u>9/26/18</u>	<u>13:30</u>
Result reported by					

Seattle Asbestos Test warrants the test results to be of a precision normal for the type and methodology employed for each sample submitted, and disclaims any other warrants, expressed or implied, including warranty of fitness for a particular purpose and warranty of merchantability. Seattle Asbestos Test accepts no legal responsibility for the purpose for which the client uses test results. By signing on this form, the clients agree to relieve Seattle Asbestos Test of any liability that may arise from the test results. Late payment may be charged of interest, invoices goes to collection causes 17-25% of collection fee. NSF is \$50.

Result Reporting method: Phone \_\_\_\_\_, Fax \_\_\_\_\_, Email XX , Pick Up Report \_\_\_\_\_

201812763

**Table C-1. Summary of Materials Sampled for Asbestos**

Sample	Material	Location	AHERA Type	HM	Result
8772.4-SC-700-093	Built up	Upper roof, South wall, center	Misc.	1	
8772.4-SC-700-094	Built up	Upper roof, North wall, center	Misc.	1	
8772.4-SC-700-095	Built Up	Upper roof, West wall, center	Misc.	1	
8772.4-SC-700-096	Torch down	Lower roof, center	Misc.	2	
8772.4-SC-700-097	Torch down	Lower roof, Northeast corner	Misc.	2	
8772.4-SC-700-098	Torch down	Lower roof, Southeast corner	Misc.	2	
8772.4-SC-700-099	Gray seam sealant	Lower roof, East wall, center	Misc.	3	
8772.4-SC-700-100	Gray seam sealant	Upper roof, Northeast corner	Misc.	3	
8772.4-SC-700-101	Gray seam sealant	Upper roof, Southeast corner	Misc.	3	

HM = homogeneous material, Misc. = miscellaneous, ND = none detected, TSI = thermal system insulation.

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.

### ANALYTICAL LABORATORY REPORT PLM by Method EPA/600/R-93/116

Attn.: Jon Havelock  
Client: Med-Tox, Northwest  
Job#: 8772.4  
Batch#: 201812763  
Samples Rec'd: 9  
Address: PO Box 1446, Auburn, WA 98071-1446  
Date Received: 9/20/2018  
Date Analyzed: 9/26/2018  
Samples Analyzed: 9

Project Loc.: Port of Tacoma - Building 700

  
Analyzed by: Xianjie (Eric) Zeng

Reviewed by: Steve (Fanyao) Zhang, President

Lab ID	Client Sample ID	Layer	Description	%	Asbestos Fibers	Non-fibrous Components	%	Non-asbestos Fibers
1	8772.4-SC-700-093	1	Black asphaltic material with sand		None detected	Asphalt/binder, Sand	3	Cellulose
		2	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		3	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	21	Glass fibers, Cellulose
		4	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		5	Yellow fibrous material		None detected	Filler	91	Glass fibers
		6	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		7	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	28	Glass fibers, Cellulose
		8	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		9	Yellow fibrous material		None detected	Filler	83	Glass fibers
		10	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		11	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	24	Glass fibers, Cellulose
		12	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		13	Yellow fibrous material		None detected	Filler	86	Glass fibers
2	8772.4-SC-700-094	1	Black asphaltic material with sand		None detected	Asphalt/binder, Sand	3	Cellulose
		2	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		3	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	32	Glass fibers, Cellulose
		4	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		5	Yellow fibrous material		None detected	Filler	81	Glass fibers
		6	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		7	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	30	Glass fibers, Cellulose
		8	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		9	Yellow fibrous material		None detected	Filler	95	Glass fibers

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.

### ANALYTICAL LABORATORY REPORT

PLM by Method EPA/600/R-93/116

Attn.: Jon Havelock  
Client: Med-Tox, Northwest  
Job#: 8772.4 Batch#: 201812763 Date Received: 9/20/2018

Samples Rec'd: 9 Date Analyzed: 9/26/2018 Samples Analyzed: 9

Project Loc.: Port of Tacoma - Building 700

Analyzed by: Xianjie (Eric) Zeng

Reviewed by: Steve (Fanyao) Zhang, President

Lab ID	Client Sample ID	Layer	Description	%	Asbestos Fibers	Non-fibrous Components	%	Non-asbestos Fibers
2	8772.4-SC-700-094	10	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		11	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	28	Glass fibers, Cellulose
		12	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		13	Yellow fibrous material		None detected	Filler	92	Glass fibers
3	8772.4-SC-700-095	1	Black asphaltic material with sand		None detected	Asphalt/binder, Sand	3	Cellulose
		2	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		3	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	20	Glass fibers, Cellulose
		4	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		5	Yellow fibrous material		None detected	Filler	81	Glass fibers
		6	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		7	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	34	Glass fibers, Cellulose
		8	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		9	Yellow fibrous material		None detected	Filler	83	Glass fibers
		10	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		11	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	27	Glass fibers, Cellulose
		12	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		13	Yellow fibrous material		None detected	Filler	92	Glass fibers
4	8772.4-SC-700-096	1	Black asphaltic material with sand		None detected	Asphalt/binder, Sand	23	Glass fibers
		2	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		3	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	28	Glass fibers, Cellulose
		4	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		5	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.


### ANALYTICAL LABORATORY REPORT

PLM by Method EPA/600/R-93/116

Attn.: Jon Havelock Client: Med-Tox, Northwest Address: PO Box 1446, Auburn, WA 98071-1446  
Job#: 8772.4 Batch#: 201812763 Date Received: 9/20/2018

Samples Rec'd: 9 Date Analyzed: 9/26/2018 Samples Analyzed: 9

Project Loc.: Port of Tacoma - Building 700

  
Analyzed by: Xianjie (Eric) Zeng

Reviewed by: Steve (Fanyao) Zhang, President

Lab ID	Client Sample ID	Layer	Description	%	Asbestos Fibers	Non-fibrous Components	%	Non-asbestos Fibers
4	8772.4-SC-700-096	6	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	20	Glass fibers, Cellulose
		7	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		8	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		9	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	35	Glass fibers, Cellulose
		10	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		11	Black asphaltic material with small sand		None detected	Asphalt/binder, Sand	10	Glass fibers
5	8772.4-SC-700-097	1	Black asphaltic material with sand		None detected	Asphalt/binder, Sand	16	Glass fibers
		2	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		3	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	21	Glass fibers, Cellulose
		4	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
6	8772.4-SC-700-098	1	Black asphaltic material with sand		None detected	Asphalt/binder, Sand	23	Glass fibers
		2	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		3	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	28	Glass fibers, Cellulose
		4	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		5	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		6	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	32	Glass fibers, Cellulose
		7	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		8	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		9	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	26	Glass fibers, Cellulose
		10	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.


### ANALYTICAL LABORATORY REPORT

PLM by Method EPA/600/R-93/116

Attn.: Jon Havelock Client: Med-Tox, Northwest  
Job#: 8772.4 Batch#: 201812763 Address: PO Box 1446, Auburn, WA 98071-1446  
Samples Rec'd: 9 Date Analyzed: 9/26/2018 Date Received: 9/20/2018

Samples Analyzed: 9



Project Loc.: Port of Tacoma - Building 700

  
Analyzed by: Xianjie (Eric) Zeng

Reviewed by: Steve (Fanyao) Zhang, President

Lab ID	Client Sample ID	Layer	Description	%	Asbestos Fibers	Non-fibrous Components	%	Non-asbestos Fibers
6	8772.4-SC-700-098	11	Black asphaltic material with small sand		None detected	Asphalt/binder, Sand	10	Glass fibers
7	8772.4-SC-700-099	1	Gray soft/elastic material		None detected	Binder, Filler	3	Cellulose
8	8772.4-SC-700-100	1	Gray soft/elastic material		None detected	Binder, Filler	2	Cellulose
9	8772.4-SC-700-101	1	Gray soft/elastic material		None detected	Binder, Filler	3	Cellulose

- 8772.4-SC-100
- 8772.4-SC-097
- 8772.4-SC-099
- 8772.4-SC-096
- 8772.4-SC-094
- 8772.4-SC-098
- 8772.4-SC-101
- 8772.4-SC-093
- 8772.4-SC-095



BUILDING 700 – ROOF PLAN  
SAMPLE LOCATIONS  
SCALE: NTS

MED-TOX		NORTHWEST	
SAFE ENVIRONMENT OF AMERICA, INC dba		OCCUPATIONAL ENVIRONMENTAL HEALTH SERVICES	
		<a href="http://www.medtoxnw@msn.com">http://www.medtoxnw@msn.com</a>	
Designed by: CHELSEA LEWIS	Date: 9/26/2018	Dwn by: JAL	Chk by: CL
		Plot Date: 	Plot Scale: AS NOTED
		Drawing Number: A.8772.4	
1701 WEST VALLEY HIGHWAY N. SUITE #1 AUBURN, WASHINGTON 98001 (253) 351-0677 (FAX)			

PROJECT NUMBER: A.8772.4

PROJECT:  
PORT OF TACOMA  
CLIENT: HELIX

Sheet  
reference  
number

October 23, 2018

Mr. Lee Davenport  
Helix Design Group, Inc.  
6021 12<sup>th</sup> Street East, Suite 201  
Tacoma, Washington 98424

Subject: Port of Tacoma 8-Building Roof Replacement  
Building 75 International Guard Station  
Hazardous Building Materials Investigation  
Tacoma, Washington  
Med-Tox Northwest Project No. A-8772.4

Dear Lee;

Shaun Childress of Med-Tox Northwest performed a limited asbestos and hazardous building materials (HBM) survey of Port of Tacoma Building 75 International Guard Station located at the end of 1675 Lincoln Avenue at the Port of Tacoma in Tacoma, Washington. The investigation was performed on September 17, 2018 and was limited to the roof system and roof top mechanical systems.

The purpose of the investigation was to assist the Port of Tacoma with communicating the presence and location of asbestos-containing materials (ACM) and potential lead hazards to employees and contractors working on the roof replacement project. It was also performed to meet the requirements for an asbestos survey by Puget Sound Clean Air Agency (PSCAA) and a good faith inspection as required by Washington State Department of Labor and Industries' Division of Occupational Safety and Health (DOSH) regulation Washington Administrative Code (WAC) 296-62-077 prior to renovation.

As required by WAC 296-62-077 and PSCAA Regulation III, Article 4, an Asbestos Hazard Emergency Response Act (AHERA) accredited building inspector performed the survey. A copy of the building inspector certificate is attached to this letter report.

## **BUILDING INFORMATION**

Building 75 is a one-story structure with approximately 224 square feet. Roof access is available via extension ladder. The roof system is a built-up roof with 5 to 6-inches of foam insulation which is applied on a wood roof substrate. Renovations will include removal and replacement of the existing roof system.

## ASBESTOS SURVEY

In total, 6 samples were collected of suspect asbestos-containing materials. Of the 6 samples collected, all were determined to be negative for asbestos by Polarized Light Microscopy (PLM) analysis. For a complete list of all materials sampled, please refer to the Summary of Materials Sampled for Asbestos attached to the laboratory report.

**Table 1** summarizes ACM identified by homogeneous material (HM) surveyed by MTNW. Friability was determined by conditions observed during the survey and by how the material behaves during mechanical demolition.

**Table 1. Summary of Asbestos-Containing Materials**

Material	Location	Friable	Quantity
There were no asbestos-containing materials identified.			

Note: This table is not to be used without the complete survey document including appendices for additional information.

Bulk samples were analyzed by Polarized Light Microscopy (PLM) dispersion staining EPA Method 600/R-93/116 by Seattle Asbestos Test, Inc. (SAT). SAT is accredited through the National Voluntary Laboratory Accreditation Program (NVLAP) of the U. S. Department of Commerce. This accreditation does not constitute endorsement, but rather a finding of laboratory competence (certification copy is attached).

## LEAD ASSESSMENT

Factory coated metal roof flashing and other metal building components are assumed to contain lead and heavy metal content.

## SUMMARY/CONCLUSION

There were no asbestos-containing materials identified in the roofing samples collected from building 75.

MTNW recommends that this survey report be placed on-site during renovation and/or demolition and copies provided to the contractor(s) bidding and performing work. WISHA, OSHA and PSCAA require that the report be on-site and available for review during the entire project duration.

WAC 296-155-176, the Lead in Construction standard, has not defined a minimum concentration for regulating lead and has clarified that lead at any detectable concentration shall be considered regulated (WAC 296-155-176, Lead). Med-Tox Northwest recommends the contractor performing demolition of the HVAC units provide a written lead compliance plan and implement the requirements of WAC 296-155-176 for any work disturbing painted surfaces.

HELIX DESIGN GROUP, INC.

Building 75 Port of Tacoma 8-Building Roof Replacement

October 23, 2018

Page 3



If you have any questions or need additional information, please contact me at (253) 351-0677.

Sincerely,

*Anthony Fullerton*

Anthony Fullerton  
Project Manager

Attachments



Photograph 1: Building 75.



Photograph 2: Built-up roof system. All suspect materials were determined to be negative for asbestos.



Photograph 3: Built-up roof system

# Certificate of Completion

This is to certify that  
**Shaun Z. Childress**  
has satisfactorily completed  
4 hours of refresher training as an  
**AHERA Building Inspector**

to comply with the training requirements of  
**TSCA Title II, 40 CFR 763 (AHERA)**

163731  
Certificate Number



Oct 18, 2017  
Date(s) of Training

Expires in 1 year.

Exam Score: N/A  
If appropriate:

*Mary Czajka*

Instructor

**Summary of Materials Sampled for Asbestos**

Sample	Material	Location	AHERA Type	HM	Result
8772.4-SC-75-050	Built up	Southeast corner	Miscellaneous	1	ND
8772.4-SC-75-051	Built up	Northwest corner	Miscellaneous	1	ND
8772.4-SC-75-052	Built up	Southwest corner	Miscellaneous	1	ND
8772.4-SC-75-053	Gray seam sealant	Northwest corner, parapet cap	Miscellaneous	2	ND
8772.4-SC-75-054	Gray seam sealant	Southwest corner, parapet cap	Miscellaneous	2	ND
8772.4-SC-75-055	Gray seam sealant	Southeast corner, parapet cap	Miscellaneous	2	ND

HM = homogeneous material, Misc. = miscellaneous, ND = none detected, TSI = thermal system insulation.

United States Department of Commerce  
National Institute of Standards and Technology



---

## Certificate of Accreditation to ISO/IEC 17025:2005

---

NVLAP LAB CODE: 200768-0

**Seattle Asbestos Test, LLC**  
Lynnwood, WA

*is accredited by the National Voluntary Laboratory Accreditation Program for specific services,  
listed on the Scope of Accreditation, for:*

### **Asbestos Fiber Analysis**

*This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005.  
This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality  
management system (refer to joint ISO-ILAC-IAF Communiqué dated January 2009).*

---

2018-10-01 through 2019-09-30

Effective Dates



  
For the National Voluntary Laboratory Accreditation Program

SEATTLE ASBESTOS TEST, LLC  
19711 Scriber Lake Rd. Suite D, Lynnwood, WA 98036  
Tel: (425) 673-9850, Fax: (425) 673-9810  
Website: seattleasbestostest.com

BATCH # 201812766

**CHAIN OF CUSTODY**

Analysis Type: Bulk Analysis  Point Count 400  Point Count 1000  Point Count Gravimetric

Turn Around Time STD Number of Samples 6 Client Job # 8772.4

Client Name Med-Tox Northwest

Address Post Office Box 1446 City Auburn State WA Zip 98071-1446

Phone 253-351-0677 Fax 253-351-0688 Email havelockj@medtoxnw.com & childresss@medtoxnw.com

Project Location: Port of Tacoma - building 75 Project Manager: Jon Havelock

Sample Condition: Good        Damaged        Severe Damage (Spillage)       

SEQ#	SAMPLE ID	SAMPLE DESCRIPTION	Lab ID	Comment	A/R
1					
2					
3					
4		<i>See attached data sheet</i>			
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					

	Print	Signature	Company Name	Date	Time
Sampled by	Shaun Childress	<i>CC</i>	Med-Tox Northwest	9/19/18	16:00
Relinquished by	Shaun Childress	<i>CC</i>	Med-Tox Northwest	9/19/18	16:00
Delivered by	FedEx				
Received by	<i>Betsy Song Betsy Song</i>		SAT	9/20/18	10:10
Analyzed by	<i>Eric Teng Kao</i>		SAT	9/26/18	15:00
Result reported by					

Seattle Asbestos Test warrants the test results to be of a precision normal for the type and methodology employed for each sample submitted, and disclaims any other warrants, expressed or implied, including warranty of fitness for a particular purpose and warranty of merchantability. Seattle Asbestos Test accepts no legal responsibility for the purpose for which the client uses test results. By signing on this form, the clients agree to relieve Seattle Asbestos Test of any liability that may arise from the test results. Late payment may be charged of interest, invoices goes to collection causes 17-25% of collection fee. NSF is \$50.

Result Reporting method: Phone       , Fax       , Email XX, Pick Up Report

2018127Ld

**Table C-1. Summary of Materials Sampled for Asbestos**

Sample	Material	Location	AHERA Type	HM	Result
8772.4-SC-75-050	Built up	Southeast corner	Misc.	1	
8772.4-SC-75-051	Built up	Northwest corner	Misc.	1	
8772.4-SC-75-052	Built up	Southwest corner	Misc.	1	
8772.4-SC-75-053	Gray seam sealant	Northwest corner, parapet cap	Misc.	2	
8772.4-SC-75-054	Gray seam sealant	Southwest corner, parapet cap	Misc.	2	
8772.4-SC-75-055	Gray seam sealant	Southeast corner, parapet cap	Misc.	2	

HM = homogeneous material, Misc. = miscellaneous, ND = none detected, TSI = thermal system insulation.

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.

### ANALYTICAL LABORATORY REPORT

PLM by Method EPA/600/R-93/116

Attn.: Jon Havelock	Client: Med-Tox, Northwest	Address: PO Box 1446, Auburn, WA 98071-1446
Job#: 8772.4	Batch#: 201812766	Date Received: 9/20/2018
Samples Rec'd: 6	Date Analyzed: 9/26/2018	Samples Analyzed: 6

Project Loc.: Port of Tacoma - Building 75

Analyzed by: Xianjie (Eric) Zeng

Reviewed by: Steve (Fanyao) Zhang, President

Lab ID	Client Sample ID	Layer	Description	%	Asbestos Fibers	Non-fibrous Components	%	Non-asbestos Fibers
1	8772.4-SC-75-050	1	Black asphaltic material with sand		None detected	Asphalt/binder, Sand	13	Glass fibers
		2	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		3	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	29	Glass fibers, Cellulose
		4	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		5	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		6	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	27	Glass fibers, Cellulose
		7	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		8	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		9	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	30	Glass fibers, Cellulose
		10	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		11	Yellow fibrous material		None detected	Filler	93	Glass fibers
		12	Black asphaltic fibrous material		None detected	Asphalt/binder, Binder/filler	68	Cellulose, Glass fibers
		13	Yellow foamy material		None detected	Synthetic foam		None detected
2	8772.4-SC-75-051	1	Black asphaltic material with sand		None detected	Asphalt/binder, Sand	13	Glass fibers
		2	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		3	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	27	Glass fibers, Cellulose
		4	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		5	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		6	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	32	Glass fibers, Cellulose
		7	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		8	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.

### ANALYTICAL LABORATORY REPORT

PLM by Method EPA/600/R-93/116

Attn.: Jon Havelock  
Client: Med-Tox, Northwest  
Job#: 8772.4  
Batch#: 201812766  
Samples Rec'd: 6  
Date Analyzed: 9/26/2018  
Address: PO Box 1446, Auburn, WA 98071-1446  
Date Received: 9/20/2018  
Samples Analyzed: 6

Project Loc.: Port of Tacoma - Building 75

Analyzed by: Xianjie (Eric) Zeng

Reviewed by: Steve (Fanyao) Zhang, President

Lab ID	Client Sample ID	Layer	Description	%	Asbestos Fibers	Non-fibrous Components	%	Non-asbestos Fibers
2	8772.4-SC-75-051	9	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	25	Glass fibers, Cellulose
		10	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		11	Yellow fibrous material		None detected	Filler	88	Glass fibers
		12	Black asphaltic fibrous material		None detected	Asphalt/binder, Binder/filler	70	Cellulose, Glass fibers
		13	Yellow foamy material		None detected	Synthetic foam		None detected
3	8772.4-SC-75-052	1	Black asphaltic material with sand		None detected	Asphalt/binder, Sand	15	Glass fibers
		2	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		3	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	32	Glass fibers, Cellulose
		4	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		5	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		6	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	31	Glass fibers, Cellulose
		7	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		8	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		9	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	29	Glass fibers, Cellulose
		10	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		11	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	30	Glass fibers, Cellulose
		12	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		13	Yellow fibrous material		None detected	Filler	88	Glass fibers
4	8772.4-SC-75-053	1	Gray soft/elastic material with paint		None detected	Binder, Filler, Paint	3	Cellulose
5	8772.4-SC-75-054	1	Gray soft/elastic material with paint		None detected	Binder, Filler, Paint	3	Cellulose
6	8772.4-SC-75-055	1	Gray soft/elastic material with paint		None detected	Binder, Filler, Paint	4	Cellulose

8772.4-SC-051



8772.4-SC-053

8772.4-SC-055

8772.4-SC-050

8772.4-SC-052

8772.4-SC-054



# BUILDING 75 – ROOF PLAN

## SAMPLE LOCATIONS

### SCALE: NTS

<b>MED-TOX</b>		SAFE ENVIRONMENT OF AMERICA, INC dba <u>NORTHWEST</u> OCCUPATIONAL ENVIRONMENTAL HEALTH SERVICES <a href="http://www.medtoxnw(msn).com">http://www.medtoxnw(msn).com</a>
Designed by: CHELSEA LEWIS	Date: 9/26/2018	
Dwn by: JAL	Chk by: CL	File Name: A.87772.4
Plot Date:	Plot Scale: AS NOTED	Drawing Number:
1701 WEST VALLEY HIGHWAY N. SUITE #1 AUBURN, WASHINGTON 98001 (253) 351-0677 (FAX)		

PROJECT NUMBER: A.8772.4

Sheet  
reference  
number

October 23, 2018

Mr. Lee Davenport  
Helix Design Group, Inc.  
6021 12<sup>th</sup> Street East, Suite 201  
Tacoma, Washington 98424

Subject: Port of Tacoma 8-Building Roof Replacement  
Building 575 Domestic Guard Station  
Hazardous Building Materials Investigation  
Tacoma, Washington  
Med-Tox Northwest Project No. A-8772.4

Dear Lee;

Shaun Childress of Med-Tox Northwest performed a limited asbestos and hazardous building materials (HBM) survey of Port of Tacoma Building 575 Domestic Guard Station located at the end of 16 East 11<sup>th</sup> Street at the Port of Tacoma in Tacoma, Washington. The investigation was performed on September 17, 2018 and was limited to the roof system which is scheduled for replacement.

The purpose of the investigation was to assist the Port of Tacoma with communicating the presence and location of asbestos-containing materials (ACM) and potential lead hazards to employees and contractors working on the roof replacement project. It was also performed to meet the requirements for an asbestos survey by Puget Sound Clean Air Agency (PSCAA) and a good faith inspection as required by Washington State Department of Labor and Industries' Division of Occupational Safety and Health (DOSH) regulation Washington Administrative Code (WAC) 296-62-077 prior to renovation.

As required by WAC 296-62-077 and PSCAA Regulation III, Article 4, an Asbestos Hazard Emergency Response Act (AHERA) accredited building inspector performed the survey. A copy of the building inspector certificate is attached to this letter report.

## **BUILDING INFORMATION**

Building 75 is a one-story structure with approximately 396 square feet. Roof access is available via extension ladder. The roof system is a built-up roof with 5 to 6-inches of foam insulation which is applied on a wood roof substrate. Renovations will include removal and replacement of the existing roof system.

## ASBESTOS SURVEY

In total, 9 samples were collected of suspect asbestos-containing materials. Of the 9 samples collected, all were determined to be negative for asbestos by Polarized Light Microscopy (PLM) analysis. For a complete list of all materials sampled, please refer to the Summary of Materials Sampled for Asbestos attached to the laboratory report.

**Table 1** summarizes ACM identified by homogeneous material (HM) surveyed by MTNW. Friability was determined by conditions observed during the survey and by how the material behaves during mechanical demolition.

**Table 1. Summary of Asbestos-Containing Materials**

Material	Location	Friable	Quantity
There were no asbestos-containing materials identified.			

Note: This table is not to be used without the complete survey document including appendices for additional information.

Bulk samples were analyzed by Polarized Light Microscopy (PLM) dispersion staining EPA Method 600/R-93/116 by Seattle Asbestos Test, LLC (SAT). SAT is accredited through the National Voluntary Laboratory Accreditation Program (NVLAP) of the U. S. Department of Commerce. This accreditation does not constitute endorsement, but rather a finding of laboratory competence (certification copy is attached).

## LEAD ASSESSMENT

Factory coated metal roof flashing and other metal building components are assumed to contain lead and heavy metal content.

## SUMMARY/CONCLUSION

There were no asbestos-containing materials identified in the roofing samples collected from building 575.

MTNW recommends that this survey report be placed on-site during renovation and/or demolition and copies provided to the contractor(s) bidding and performing work. WISHA, OSHA and PSCAA require that the report be on-site and available for review during the entire project duration.

WAC 296-155-176, the Lead in Construction standard, has not defined a minimum concentration for regulating lead and has clarified that lead at any detectable concentration shall be considered regulated (WAC 296-155-176, Lead). Med-Tox Northwest recommends the contractor performing demolition of painted roof components provide a written lead compliance plan and implement the requirements of WAC 296-155-176 for any work disturbing painted surfaces.

HELIX DESIGN GROUP, INC.

Building 575 Port of Tacoma 8-Building Roof Replacement

October 23, 2018

Page 3



If you have any questions or need additional information, please contact me at (253) 351-0677.

Sincerely,

Jon A. Havelock, CSP, CHMM

Senior Project Manager

Attachments

HELIX DESIGN GROUP, INC.

Building 575 Port of Tacoma 8-Building Roof Replacement

October 23, 2018

Page 4

SAFE ENVIRONMENT OF AMERICA, INC. d/b/a  
**MED-TOX**  
NORTHWEST



Photograph 1: Building 575.



Photograph 2: Built-up roof system. All suspect materials were determined to be negative for asbestos.

# Certificate of Completion

This is to certify that  
**Shaun Z. Childress**  
has satisfactorily completed  
4 hours of refresher training as an  
**AHERA Building Inspector**

to comply with the training requirements of  
**TSCA Title II, 40 CFR 763 (AHERA)**

163731  
Certificate Number



Oct 18, 2017  
Date(s) of Training

Expires in 1 year.

Exam Score: N/A  
If appropriate:

*Mary Czajka*

Instructor

### Summary of Materials Sampled for Asbestos

Sample	Material	Location	AHERA Type	HM	Result
8772.4-SC-575-056	Built up	Northeast corner	Miscellaneous	1	ND
8772.4-SC-575-057	Built up	Southeast corner	Miscellaneous	1	ND
8772.4-SC-575-058	Built up	Southwest corner	Miscellaneous	1	ND
8772.4-SC-575-059	Gray seam sealant	Parapet cap, Northeast corner	Miscellaneous	2	ND
8772.4-SC-575-060	Gray seam sealant	Parapet cap, Northwest corner	Miscellaneous	2	ND
8772.4-SC-575-061	Gray seam sealant	Parapet cap, Southwest corner	Miscellaneous	2	ND
8772.4-SC-575-062	Gray seam sealant	Parapet wall, vertical seam, Northeast corner	Miscellaneous	3	ND
8772.4-SC-575-063	Gray seam sealant	Parapet wall, vertical seam, Northwest corner	Miscellaneous	3	ND
8772.4-SC-575-064	Gray seam sealant	Parapet wall, vertical seam, Southwest corner	Miscellaneous	3	ND

HM = homogeneous material, ND = none detected.

United States Department of Commerce  
National Institute of Standards and Technology



---

## Certificate of Accreditation to ISO/IEC 17025:2005

---

NVLAP LAB CODE: 200768-0

**Seattle Asbestos Test, LLC**  
Lynnwood, WA

*is accredited by the National Voluntary Laboratory Accreditation Program for specific services,  
listed on the Scope of Accreditation, for:*

### **Asbestos Fiber Analysis**

*This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005.  
This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality  
management system (refer to joint ISO-ILAC-IAF Communiqué dated January 2009).*

---

2018-10-01 through 2019-09-30

Effective Dates



  
For the National Voluntary Laboratory Accreditation Program

SEATTLE ASBESTOS TEST, LLC  
19711 Scriber Lake Rd. Suite D, Lynnwood, WA 98036  
Tel: (425) 673-9850, Fax: (425) 673-9810  
Website: seattleasbestostest.com

BATCH # 201812745

## CHAIN OF CUSTODY

Analysis Type: Bulk Analysis X Point Count 400 \_\_\_\_\_ Point Count 1000 \_\_\_\_\_ Point Count Gravimetric \_\_\_\_\_

Turn Around Time STD Number of Samples 9 Client Job # 8772.4

Client Name Med-Tox Northwest

Address Post Office Box 1446 City Auburn State WA Zip 98071-1446

Phone 253-351-0677 Fax 253-351-0688 Email havelockj@medtoxnw.com & childresss@medtoxnw.com

Project Location: Port of Tacoma - building 575 Project Manager: Jon Havelock

Sample Condition: Good \_\_\_\_\_ Damaged \_\_\_\_\_ Severe Damage (Spillage) \_\_\_\_\_

SEQ#	SAMPLE ID	SAMPLE DESCRIPTION	Lab ID	Comment	A/R
1					
2		<i>See attached</i>			
3		<i>datasheet</i>			
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					

	Print	Signature	Company Name	Date	Time
Sampled by	Shaun Childress	<i>SC</i>	Med-Tox Northwest	9/19/18	16:00
Relinquished by	Shaun Childress	<i>CC</i>	Med-Tox Northwest	9/19/18	16:00
Delivered by	FedEx				
Received by	<i>Betsylind BeBepong</i>		SAT	9/20/18	10:10
Analyzed by	<i>Eric Zeng</i>		SAT	9/26/18	10:38
Result reported by					

Seattle Asbestos Test warrants the test results to be of a precision normal for the type and methodology employed for each sample submitted, and disclaims any other warrants, expressed or implied, including warranty of fitness for a particular purpose and warranty of merchantability. Seattle Asbestos Test accepts no legal responsibility for the purpose for which the client uses test results. By signing on this form, the clients agree to relieve Seattle Asbestos Test of any liability that may arise from the test results. Late payment may be charged of interest, invoices goes to collection causes 17-25% of collection fee. NSF is \$50.

Result Reporting method: Phone \_\_\_\_\_, Fax \_\_\_\_\_, Email XX, Pick Up Report \_\_\_\_\_

201812765

Table C-1. Summary of Materials Sampled for Asbestos

Sample	Material	Location	AHERA Type	HM	Result
8772.4-SC-575-056	Built up	Northeast corner	Misc.	1	
8772.4-SC-575-057	Built up	Southeast corner	Misc.	1	
8772.4-SC-575-058	Built up	Southwest corner	Misc.	1	
8772.4-SC-575-059	Gray seam sealant	Parapet cap, Northeast corner	Misc.	2	
8772.4-SC-575-060	Gray seam sealant	Parapet cap, Northwest corner	Misc.	2	
8772.4-SC-575-061	Gray seam sealant	Parapet cap, Southwest corner	Misc.	2	
8772.4-SC-575-062	Gray seam sealant	Parapet wall, vertical seam, Northeast corner	Misc.	3	
8772.4-SC-575-063	Gray seam sealant	Parapet wall, vertical seam, Northwest corner	Misc.	3	
8772.4-SC-575-064	Gray seam sealant	Parapet wall, vertical seam, Southwest corner	Misc.	3	

HM = homogeneous material, Misc. = miscellaneous, ND = none detected, TSI = thermal system insulation.

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.

### ANALYTICAL LABORATORY REPORT

PLM by Method EPA/600/R-93/116

Attn.: Jon Havelock

Client: Med-Tox, Northwest

Address: PO Box 1446, Auburn, WA 98071-1446

Job#: 8772.4

Batch#: 201812765

Date Received: 9/20/2018

Samples  
Rec'd: 9

Date Analyzed: 9/26/2018

Samples Analyzed: 9

Project Loc.: Port of Tacoma - Building 575

Analyzed by: Xianjie (Eric) Zeng

Reviewed by: Steve (Fanyao) Zhang, President

Lab ID	Client Sample ID	Layer	Description	%	Asbestos Fibers	Non-fibrous Components	%	Non-asbestos Fibers
1	8772.4-SC-575-056	1	Black asphaltic material with sand		None detected	Asphalt/binder, Sand	8	Glass fibers
		2	Black asphaltic material		None detected	Asphalt/binder	3	Cellulose
		3	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	29	Glass fibers, Cellulose
		4	Black asphaltic material		None detected	Asphalt/binder	3	Cellulose
		5	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	28	Glass fibers, Cellulose
		6	Black asphaltic material		None detected	Asphalt/binder	3	Cellulose
		7	Orange fibrous material		None detected	Filler	90	Glass fibers
		8	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	30	Glass fibers, Cellulose
		9	Yellow foamy material		None detected	Synthetic foam		None detected
2	8772.4-SC-575-057	1	Black asphaltic material with sand		None detected	Asphalt/binder, Sand	7	Glass fibers
		2	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose
		3	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	31	Glass fibers, Cellulose
		4	Black asphaltic material		None detected	Asphalt/binder	4	Cellulose
		5	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	35	Glass fibers, Cellulose
		6	Black asphaltic material		None detected	Asphalt/binder	3	Cellulose
		7	Orange fibrous material		None detected	Filler	90	Glass fibers
		8	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	36	Glass fibers, Cellulose
		9	Yellow foamy material		None detected	Synthetic foam		None detected
3	8772.4-SC-575-058	1	Black asphaltic material with sand		None detected	Asphalt/binder, Sand	5	Glass fibers
		2	Black asphaltic material		None detected	Asphalt/binder	2	Cellulose

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.

### ANALYTICAL LABORATORY REPORT PLM by Method EPA/600/R-93/116

Attn.: Jon Havelock  
Job#: 8772.4  
Samples Rec'd: 9  
Project Loc.: Port of Tacoma - Building 575

Client: Med-Tox, Northwest  
Batch#: 201812765  
Date Analyzed: 9/26/2018

Address: PO Box 1446, Auburn, WA 98071-1446  
Date Received: 9/20/2018  
Samples Analyzed: 9

Analyzed by: Xianjie (Eric) Zeng

Reviewed by: Steve (Fanyao) Zhang, President

Lab ID	Client Sample ID	Layer	Description	%	Asbestos Fibers	Non-fibrous Components	%	Non-asbestos Fibers
3	8772.4-SC-575-058	3	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	26	Glass fibers, Cellulose
		4	Black asphaltic material		None detected	Asphalt/binder	4	Cellulose
		5	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	24	Glass fibers, Cellulose
		6	Black asphaltic material		None detected	Asphalt/binder	3	Cellulose
		7	Orange fibrous material		None detected	Filler	88	Glass fibers
		8	Black asphaltic material with fibrous material		None detected	Asphalt/binder, Filler	28	Glass fibers, Cellulose
		9	Yellow foamy material		None detected	Synthetic foam		None detected
4	8772.4-SC-575-059	1	Gray/black soft/elastic material		None detected	Binder, Filler	3	Cellulose
5	8772.4-SC-575-060	1	Gray/black soft/elastic material		None detected	Binder, Filler	4	Cellulose
6	8772.4-SC-575-061	1	Gray/black soft/elastic material		None detected	Binder, Filler	3	Cellulose
7	8772.4-SC-575-062	1	Gray/black soft/elastic material		None detected	Binder, Filler	3	Cellulose
8	8772.4-SC-575-063	1	Gray/black soft/elastic material		None detected	Binder, Filler	3	Cellulose
9	8772.4-SC-575-064	1	Gray/black soft/elastic material		None detected	Binder, Filler	4	Cellulose




BUILDING 575 – ROOF PLAN  
SAMPLE LOCATIONS  
SCALE: NTS

Sheet reference number  
Sheet 1 OF 1

**MED-TOX**  
NORTHWEST  
OCCUPATIONAL ENVIRONMENTAL MEDICAL SERVICES  
1701 WEST VALLEY HIGHWAY N, SUITE #1  
(206) 355-0588 (FAX)

PROJECT NUMBER: A.8772.4  
PROJECT: PORT OF TACOMA  
CLIENT: HELIX



Symbol	Description	Date	Approved

Designed by: CHELSEA LEWIS	Date: 9/26/2018
Drawn by: JAL	Check by: CL
File Name: A.8772.4	
Plot Date:	
Plot Scale: AS NOTED	
Drawing Number:	