




February 19, 2026

IMPORTANT PRODUCT SERVICE BULLETIN

This Notice Applies to Ronin 2805-11 & 1011-11 Power Ascenders Produced after January 2024



Spartaco recently documented three instances where newly received Ronin ascender units failed pre-flight checks performed by the customer. The pre-flight checks detected that the thumbwheel would not freely return to the off position, which could cause the unit to operate unexpectedly.

This failure would be classified as a critical safety failure when operating at height that could lead to a serious injury of the user.

All units were brand new out of the box condition. The identified units were:

PN 2805-11 SN 5132

PN 1011-11 SN 1516

PN 1011-11 SN 1580

This service bulletin applies to all Ronin units manufactured after January 2024.

If you have a manufactured unit within this time frame, please take immediate steps to conduct a pre-flight checklist ([click here for instructions](#)). If after completing this procedure the unit operates correctly no further action is necessary.

If after completing the pre-flight checklist procedure, the unit operates un-commanded after releasing the thumbwheel switch you should immediately return your ascenders for rework, using the return material authorization process:

<https://roninpowerascender.com/rma/>

Spartaco Tool Group will provide this service free of charge.