

**Table 1. Summary of Materials Sampled for Asbestos**

Sample	Material	Location	AHERA Type	HM	Result
2338 11 <sup>th</sup> Street					
Self-Storage					
8842.1-2338-01	Batt insulation foil paper black mastic	Exterior walls	TSI	01	
8842.1-2338-02	Batt insulation foil paper black mastic	Exterior walls	TSI	01	
8842.1-2338-03	Batt insulation foil paper black mastic	Exterior walls	TSI	01	
8842.1-2338-04	Heavy orange peel textured GWB system	Restrooms	Surfacing	02	
8842.1-2338-05	Heavy orange peel textured GWB system	Restrooms	Surfacing	02	
8842.1-2338-06	Heavy orange peel textured GWB system	2 <sup>nd</sup> floor	Surfacing	02	
8842.1-2338-07	Heavy orange peel textured GWB system	2 <sup>nd</sup> floor	Surfacing	02	
8842.1-2338-08	Heavy orange peel textured GWB system	2 <sup>nd</sup> floor	Surfacing	02	
8842.1-2338-09	Rough textured GWB system	hallway	Surfacing	03	
8842.1-2338-10	Rough textured GWB system	hallway	Surfacing	03	
8842.1-2338-11	Rough textured GWB system	hallway	Surfacing	03	
8842.1-2338-12	Un-textured GWB system	South hallway to stairs	Misc.	04	
8842.1-2338-13	Un-textured GWB system	South hallway to stairs	Misc.	04	
8842.1-2338-14	4-inch brown cove base and mastic	Restroom	Misc.	05	
8842.1-2338-15	4-inch brown cove base and mastic	Restroom	Misc.	05	
8842.1-2338-16	9-inch tan VFT and black mastic	Main floor	Misc.	06	
8842.1-2338-17	9-inch tan VFT and black mastic	Main floor	Misc.	06	
8842.1-2338-18	12-inch red square pattern self-stick floor tile	Restroom	Misc.	07	
8842.1-2338-19	12-inch red square pattern self-stick floor tile	Restroom	Misc.	07	
8842.1-2338-20	Tan/beige floor coating	East end of hall	Misc.	08	

## Hazardous Building Materials Survey—Port of Tacoma

Sample	Material	Location	AHERA Type	HM	Result
8842.1-2338-21	Tan/beige floor coating	East end of hall	Misc.	08	
8842.1-2338-22	Leveling compound	Wood floor	Misc.	09	
8842.1-2338-23	Leveling compound	Wood floor	Misc.	09	
8842.1-2338-24	Carpet mastic	2 <sup>nd</sup> floor office	Misc.	10	
8842.1-2338-25	Carpet mastic	2 <sup>nd</sup> floor office	Misc.	10	
8842.1-2338-26	Batt insulation black paper and mastic	2 <sup>nd</sup> floor office walls behind paneling	TSI	11	
8842.1-2338-27	Batt insulation black paper and mastic	2 <sup>nd</sup> floor office walls behind paneling	TSI	11	
8842.1-2338-28	Batt insulation black paper and mastic	2 <sup>nd</sup> floor office walls behind paneling	TSI	11	
<b>Graphics</b>					
8842.1-2338-29	Orange peel textured GWB system	Office area	Surfacing	12	
8842.1-2338-30	Orange peel textured GWB system	Office area	Surfacing	12	
8842.1-2338-31	Orange peel textured GWB system	Office area	Surfacing	12	
8842.1-2338-32	Un-textured GWB system	NE section main shop	Misc.	13	
8842.1-2338-33	Un-textured GWB system	NE section main shop	Misc.	13	
8842.1-2338-34	Brick mortar	Main shop area	Misc.	14	
8842.1-2338-35	Brick mortar	Main shop area	Misc.	14	
8842.1-2338-36	2-inch white cove base and mastic	Office area	Misc.	15	
8842.1-2338-37	2-inch white cove base and mastic	Office area	Misc.	15	
8842.1-2338-38	4-inch black cove base and yellow mastic	Office area restroom	Misc.	16	
8842.1-2338-39	4-inch black cove base and yellow mastic	Office area restroom	Misc.	16	
8842.1-2338-40	2-inch brown cove base and orange mastic	Office area back storage	Misc.	17	
8842.1-2338-41	2-inch brown cove base and orange mastic	Office area back storage	Misc.	17	
8842.1-2338-42	Brown/yellow terrazzo pattern SVF- top layer	Office area restroom and back storage area	Misc.	18	

## Hazardous Building Materials Survey—Port of Tacoma

Sample	Material	Location	AHERA Type	HM	Result
8842.1-2338-43	Brown/yellow terrazzo pattern SVF- top layer	Office area restroom and back storage area	Misc.	18	
8842.1-2338-44	Off-white floor tile and mastic- bottom layer	Office area restroom and back storage area	Misc.	19	
8842.1-2338-45	Off-white floor tile and mastic- bottom layer	Office area restroom and back storage area	Misc.	19	
8842.1-2338-46	9-inch brown VFT and black mastic	NE section	Misc.	20	
8842.1-2338-47	9-inch brown VFT and black mastic	NE section	Misc.	20	
8842.1-2338-48	4-inch square pattern GWB panels	Shop area ceiling	Misc.	21	
8842.1-2338-49	4-inch square pattern GWB panels	Shop area ceiling	Misc.	21	
8842.1-2338-50	2-x 4-foot ACT	Office area	Misc.	22	
8842.1-2338-51	2-x 4-foot ACT	Office area	Misc.	22	
8842.1-2338-52	Fiberboard ceiling panel	NE section	Misc.	23	
8842.1-2338-53	Fiberboard ceiling panel	NE section	Misc.	23	
8842.1-2338-54	Window glaze	Shop area-south side	Misc.	24	
8842.1-2338-55	Window glaze	Shop area-south side	Misc.	24	
8842.1-2338-56	White wall caulk	Shop area metal framed build-out	Misc.	25	
8842.1-2338-57	White wall caulk	Shop area metal framed build-out	Misc.	25	
8842.1-2338-58	CMU mortar and paint coating	Exterior- east	Misc.	26	
8842.1-2338-59	CMU mortar and paint coating	Exterior- east	Misc.	26	
8842.1-2338-60	CMU mortar and paint coating	Exterior- north	Misc.	26	
8842.1-2338-61	Window frame caulk	Office exterior windows	Misc.	27	
8842.1-2338-62	Window frame caulk	Office exterior windows	Misc.	27	
<b>Roof</b>					
8842.1-2338-63	Silver coat paint (HM28) and built-up roofing (HM29)	South section (over self-storage)	Misc.	28/29	

## Hazardous Building Materials Survey—Port of Tacoma

Sample	Material	Location	AHERA Type	HM	Result
8842.1-2338-64	Silver coat paint (HM28) and built-up roofing (HM29)	Center section- west (over graphics shop)	Misc.	28/29	
8842.1-2338-65	Silver coat paint (HM28) and built-up roofing (HM29)	North section- center (over graphics shop)	Misc.	28/29	
8842.1-2338-66	Silver coat paint	South side- west over self-storage	Misc.	28	
8842.1-2338-67	Silver coat paint	Center section (over graphics)	Misc.	28	
8842.1-2338-68	Silver coat paint	North side (over graphics)	Misc.	28	
8842.1-2338-69	Black roof sealant	South side (east)	Misc.	30	
8842.1-2338-70	Black roof sealant	South side (north)	Misc.	30	
8842.1-2338-71	Black roof sealant	Center (east)	Misc.	30	

GWB = gypsum wallboard, HM = homogeneous material, Misc. = miscellaneous, ND = none detected, SVF = sheet vinyl flooring, TSI = thermal system insulation.

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.

### ANALYTICAL LABORATORY REPORT

PLM by Method EPA/600/R-93/116

Attn.: Anthony Fullerton

Client: Med-Tox, Northwest

Address: PO Box 1446, Auburn, WA 98071-1446

Job#: 8842.1

Batch#: 201911093

Date Received: 6/27/2019

Samples Rec'd: 71

Date Analyzed: 7/3/2019

Samples Analyzed: 71

Project Loc.: 2338 11th St, Tacoma, WA

Analyzed by:  Yajun Gao

Reviewed by:  Steve (Fanyao) Zhang, President

Lab ID	Client Sample ID	Layer	Description	%	Asbestos Fibers	Non-fibrous Components	%	Non-asbestos Fibers
1	8842.1-2338-01	1	Silver foil		None detected	Foil/binder		None detected
		2	Tan paper with black mastic		None detected	Filler, Asphalt/binder	72	Cellulose
		3	Yellow fibrous material		None detected	Filler	90	Glass fibers
2	8842.1-2338-02	1	Silver foil		None detected	Foil/binder		None detected
		2	Tan paper with black mastic		None detected	Filler, Asphalt/binder	70	Cellulose
		3	Yellow fibrous material		None detected	Filler	92	Glass fibers
3	8842.1-2338-03	1	Silver foil		None detected	Foil/binder		None detected
		2	Tan paper with black mastic		None detected	Filler, Asphalt/binder	70	Cellulose
		3	Yellow fibrous material		None detected	Filler	90	Glass fibers
4	8842.1-2338-04	1	Off-white powdery material with yellow paint	2	Chrysotile	Binder/filler, Paint	4	Cellulose
		2	White chalky material with paper		None detected	Binder/filler, Gypsum/binder	22	Cellulose, Glass fibers
5	8842.1-2338-05	1	White powdery material with tan paint		None detected	Binder/filler, Paint	3	Cellulose
		2	Heavy orange chalky material with paper		None detected	Binder/filler, Gypsum/binder	24	Cellulose, Glass fibers
6	8842.1-2338-06	1	White powdery material with paint		None detected	Binder/filler, Paint	3	Cellulose
		2	White chalky material with paper		None detected	Binder/filler, Gypsum/binder	25	Cellulose, Glass fibers
7	8842.1-2338-07	1	White powdery material with paint		None detected	Binder/filler, Paint	4	Cellulose
		2	Heavy orange chalky material with paper		None detected	Binder/filler, Gypsum/binder	26	Cellulose, Glass fibers
8	8842.1-2338-08	1	White powdery material with paint		None detected	Binder/filler, Paint	3	Cellulose
		2	Heavy orange chalky material with paper		None detected	Binder/filler, Gypsum/binder	25	Cellulose, Glass fibers
9	8842.1-2338-09	1	Off-white powdery material with paint	2	Chrysotile	Binder/filler, Paint	4	Cellulose
		2	White chalky material with paper		None detected	Binder/filler, Gypsum/binder	25	Cellulose, Glass fibers
10	8842.1-2338-10	1	Off-white powdery material with paint	2	Chrysotile	Binder/filler, Paint	5	Cellulose

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.

### ANALYTICAL LABORATORY REPORT

PLM by Method EPA/600/R-93/116

Attn.: Anthony Fullerton

Client: Med-Tox, Northwest

Address: PO Box 1446, Auburn, WA 98071-1446

Job#: 8842.1

Batch#: 201911093


Date Received: 6/27/2019

Samples Rec'd: 71

Date Analyzed: 7/3/2019

Samples Analyzed: 71

Project Loc.: 2338 11th St, Tacoma, WA

Analyzed by:  Yajun Gao

Reviewed by: Steve (Fanyao) Zhang, President 

Sample ID	Sample Ref ID	Sample Number	Sample Description	Asbestos Type	Matrix	Count	Notes
10	8842.1-2338-10	2	White chalky material with paper	None detected	Binder/filler, Gypsum/binder	24	Cellulose, Glass fibers
11	8842.1-2338-11	1	Off-white powdery material with paint	2 Chrysotile	Binder/filler, Paint	5	Cellulose
		2	Off-white powdery material with paper	2 Chrysotile	Binder/filler	30	Cellulose
		3	White chalky material with paper	None detected	Binder/filler, Gypsum/binder	22	Cellulose
12	8842.1-2338-12	1	White powdery material	None detected	Filler, Binder	3	Cellulose
		2	White chalky material with paper	None detected	Binder/filler, Gypsum/binder	25	Cellulose, Glass fibers
13	8842.1-2338-13	1	White powdery material	None detected	Filler, Binder	4	Cellulose
		2	White powdery material with paper	None detected	Binder/filler	28	Cellulose
		3	White chalky material with paper	None detected	Binder/filler, Gypsum/binder	20	Cellulose
14	8842.1-2338-14	1	Brown rubbery material	None detected	Rubber/binder	2	Cellulose
		2	Brown mastic	None detected	Mastic/binder	3	Cellulose
15	8842.1-2338-15	1	Brown rubbery material	None detected	Rubber/binder	2	Cellulose
		2	Brown mastic	None detected	Mastic/binder	2	Cellulose
		3	Trace white powdery material with paint	None detected	Binder/filler, Paint	4	Cellulose
16	8842.1-2338-16	1	Tan tile with gray paint	2 Chrysotile	Vinyl/binder, Mineral grains, Paint	2	Cellulose
		2	Black mastic	2 Chrysotile	Mastic/binder	3	Cellulose
17	8842.1-2338-17	1	Tan tile with	2 Chrysotile	Vinyl/binder, Mineral grains	2	Cellulose
		2	Black mastic with debris	2 Chrysotile	Mastic/binder	4	Cellulose
18	8842.1-2338-18	1	Red vinyl	None detected	Vinyl/binder		None detected
		2	Gray tile	None detected	Vinyl/binder, Mineral grains	2	Cellulose
		3	Clear mastic with debris	None detected	Mastic/binder, Debris	3	Cellulose
19	8842.1-2338-19	1	Red vinyl	None detected	Vinyl/binder		None detected
		2	Gray tile	None detected	Vinyl/binder, Mineral grains	2	Cellulose
		3	Clear mastic with debris	None detected	Mastic/binder, Debris	4	Cellulose

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.

### ANALYTICAL LABORATORY REPORT PLM by Method EPA/600/R-93/116

Attn.: Anthony Fullerton  
Job#: 8842.1  
Samples Rec'd: 71

Client: Med-Tox, Northwest  
Batch#: 201911093  
Date Analyzed: 7/3/2019

Address: PO Box 1446, Auburn, WA 98071-1446  
Date Received: 6/27/2019

Samples Analyzed: 71

Project Loc.: 2338 11th St, Tacoma, WA

  
Analyzed by: Yajin Gao

Reviewed by: Steve (Fanyao) Zhang, President 

20	8842.1-2338-20	1	Tan/beige paint	None detected	Paint/binder	2	Cellulose
21	8842.1-2338-21	1	Tan/beige paint	None detected	Paint/binder	2	Cellulose
		2	Trace gray sandy/brittle material	None detected	Sand, Filler, Binder	3	Cellulose
22	8842.1-2338-22	1	White brittle material with paint	None detected	Filler, Binder, Paint	2	Cellulose
23	8842.1-2338-23	1	White brittle material with paint and debris	None detected	Filler, Binder, Paint, Debris	3	Cellulose
24	8842.1-2338-24	1	Multi-colored woven fibrous material	None detected	Filler, Binder	85	Synthetic fibers
		2	Gray foamy material	None detected	Synthetic foam		None detected
		3	Yellow mastic with wood debris	None detected	Mastic/binder, Wood debris	5	Cellulose
25	8842.1-2338-25	1	Multi-colored woven fibrous material	None detected	Filler, Binder	80	Synthetic fibers
		2	Gray foamy material	None detected	Synthetic foam		None detected
		3	Trace yellow mastic	None detected	Mastic/binder	2	Cellulose
26	8842.1-2338-26	1	Black paper with black mastic	None detected	Filler, Asphalt/binder	72	Cellulose
		2	Black fibrous material	None detected	Filler, Glass beads	90	Glass fibers
27	8842.1-2338-27	1	Black paper with black mastic	None detected	Filler, Asphalt/binder	68	Cellulose
		2	Black fibrous material	None detected	Filler, Glass beads	92	Glass fibers
28	8842.1-2338-28	1	Black paper with black mastic	None detected	Filler, Asphalt/binder	70	Cellulose
		2	Black fibrous material	None detected	Filler, Glass beads	90	Glass fibers
29	8842.1-2338-29	1	White powdery material with paint	None detected	Binder/filler, Paint	5	Cellulose
		2	White chalky material with paper	None detected	Binder/filler, Gypsum/binder	24	Cellulose
30	8842.1-2338-30	1	White powdery material with paint	None detected	Binder/filler, Paint	3	Cellulose
		2	White powdery material with paper	None detected	Binder/filler	30	Cellulose
		3	White chalky material with paper	None detected	Binder/filler, Gypsum/binder	25	Cellulose
31	8842.1-2338-31	1	White powdery material with paint	None detected	Binder/filler, Paint	4	Cellulose

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.

### ANALYTICAL LABORATORY REPORT

PLM by Method EPA/600/R-93/116

Attn.: Anthony Fullerton	Client: Med-Tox, Northwest	Address: PO Box 1446, Auburn, WA 98071-1446
Job#: 8842.1	Batch#: 201911093	Date Received: 6/27/2019
Samples Rec'd: 71	Date Analyzed: 7/3/2019	Samples Analyzed: 71

Project Loc.: 2338 11th St, Tacoma, WA

Y. Gao

Reviewed by: Steve (Fanyao) Zhang, President

S. Zhang

Sample ID	Job ID	Sample Number	Description	Result	Identified Components	Count	Material Type
31	8842.1-2338-31	2	White chalky material with paper	None detected	Binder/filler, Gypsum/binder	25	Cellulose
32	8842.1-2338-32	1	White chalky material with paper	None detected	Binder/filler, Gypsum/binder	23	Cellulose
33	8842.1-2338-33	1	White powdery material with paint	None detected	Binder/filler, Paint	3	Cellulose
		2	White powdery material with paper	None detected	Binder/filler	32	Cellulose
		3	White chalky material with paper	None detected	Binder/filler, Gypsum/binder	22	Cellulose
34	8842.1-2338-34	1	Loose gray sandy/brittle material with paint	None detected	Sand, Filler, Binder, Paint	3	Cellulose
35	8842.1-2338-35	1	Loose gray sandy/brittle material with paint	None detected	Sand, Filler, Binder, Paint	2	Cellulose
36	8842.1-2338-36	1	White plastic material	None detected	Plastic		None detected
		2	White soft/elastic material	None detected	Binder, Filler, Fine particles	4	Cellulose
		3	Yellow mastic	None detected	Mastic/binder	2	Cellulose
37	8842.1-2338-37	1	White plastic material	None detected	Plastic		None detected
		2	White soft/elastic material	None detected	Binder, Filler, Fine particles	3	Cellulose
		3	Yellow mastic	None detected	Mastic/binder	2	Cellulose
		4	Trace white powdery material with paint	None detected	Binder/filler, Paint	2	Cellulose
38	8842.1-2338-38	1	Black plastic material	None detected	Plastic		None detected
		2	Black soft/elastic material	None detected	Binder, Filler, Fine particles	3	Cellulose
		3	Yellow mastic	None detected	Mastic/binder	2	Cellulose
		4	White paint	None detected	Paint/binder	2	Cellulose
39	8842.1-2338-39	1	Black plastic material	None detected	Plastic		None detected
		2	Black soft/elastic material	None detected	Binder, Filler, Fine particles	4	Cellulose
		3	Yellow mastic	None detected	Mastic/binder	2	Cellulose
		4	White/yellow paint	None detected	Paint/binder	2	Cellulose
40	8842.1-2338-40	1	Brown soft/elastic material	None detected	Binder, Filler, Fine particles	3	Cellulose

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.

### ANALYTICAL LABORATORY REPORT

PLM by Method EPA/600/R-93/116

Attn.: Anthony Fullerton  
Job#: 8842.1  
Samples Rec'd: 71

Client: Med-Tox, Northwest  
Batch#: 201911093  
Date Analyzed: 7/3/2019

Address: PO Box 1446, Auburn, WA 98071-1446  
Date Received: 6/27/2019  
Samples Analyzed: 71

Project Loc.: 2338 11th St, Tacoma, WA

Analyzed by:  Yajun Gao

Reviewed by: Steve (Fanyao) Zhang, President 

Sample ID	Sample Description	Count	Material Type	Asbestos Type	Matrix	Count	Material Type
40	8842.1-2338-40	2	Orange mastic	None detected	Mastic/binder	2	Cellulose
41	8842.1-2338-41	1	Brown soft/elastic material	None detected	Binder, Filler, Fine particles	4	Cellulose
		2	Orange mastic	None detected	Mastic/binder	2	Cellulose
42	8842.1-2338-42	1	Brown/yellow sheet vinyl	None detected	Vinyl/binder		None detected
		2	White fibrous material with mastic	48 Chrysotile	Binder/filler, Mastic/binder	30	Cellulose
43	8842.1-2338-43	1	Brown/yellow sheet vinyl	None detected	Vinyl/binder		None detected
		2	White fibrous material with mastic	50 Chrysotile	Binder/filler, Mastic/binder	28	Cellulose
		3	Off-white tile	2 Chrysotile	Vinyl/binder, Mineral grains	2	Cellulose
		4	Gray sandy/brittle material with trace paint	None detected	Sand, Filler, Binder, Paint	3	Cellulose
44	8842.1-2338-44	1	Trace white fibrous material with mastic	46 Chrysotile	Binder/filler, Mastic/binder	25	Cellulose
		2	Off-white tile	2 Chrysotile	Vinyl/binder, Mineral grains	2	Cellulose
		3	Black mastic	None detected	Mastic/binder	3	Cellulose
		4	Red brittle material	None detected	Filler, Binder	2	Cellulose
45	8842.1-2338-45	1	Trace white fibrous material with mastic	48 Chrysotile	Binder/filler, Mastic/binder	26	Cellulose
		2	Off-white tile	2 Chrysotile	Vinyl/binder, Mineral grains	2	Cellulose
		3	Black mastic	None detected	Mastic/binder	4	Cellulose
		4	Red brittle material	None detected	Filler, Binder	2	Cellulose
46	8842.1-2338-46	1	Brown tile	2 Chrysotile	Vinyl/binder, Mineral grains	2	Cellulose
		2	Black mastic	3 Chrysotile	Mastic/binder	3	Cellulose
47	8842.1-2338-47	1	Brown tile	2 Chrysotile	Vinyl/binder, Mineral grains	3	Cellulose
		2	Black mastic	3 Chrysotile	Mastic/binder	4	Cellulose
48	8842.1-2338-48	1	White chalky material with paint and paper	None detected	Binder/filler, Gypsum/binder, Paint, Tiny sand	35	Cellulose

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0

Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.

### ANALYTICAL LABORATORY REPORT

PLM by Method EPA/600/R-93/116

Attn.: Anthony Fullerton  
Job#: 8842.1  
Samples Rec'd: 71

Client: Med-Tox, Northwest  
Batch#: 201911093  
Date Analyzed: 7/3/2019

Address: PO Box 1446, Auburn, WA 98071-1446  
Date Received: 6/27/2019  
Samples Analyzed: 71

Project Loc.: 2338 11th St, Tacoma, WA

Analyzed by: Yajun Gao

Reviewed by: Steve (Fanyao) Zhang, President

49	8842.1-2338-49	1	White chalky material with paint and paper	<b>None detected</b>	Binder/filler, Gypsum/binder, Paint, Tiny sand	34	Cellulose
50	8842.1-2338-50	1	Gray fibrous material with white paint	<b>None detected</b>	Paint, Filler, Perlite	65	Cellulose
51	8842.1-2338-51	1	Gray fibrous material with white paint	<b>None detected</b>	Paint, Filler, Perlite	68	Cellulose
52	8842.1-2338-52	1	Tan powdery material with paint	<b>2 Chrysotile</b>	Filler, Paint/binder	3	Cellulose
		2	Brown paper	<b>None detected</b>	Filler	75	Cellulose
53	8842.1-2338-53	1	Tan powdery material with paint	<b>2 Chrysotile</b>	Filler, Paint/binder	4	Cellulose
		2	Brown paper	<b>None detected</b>	Filler	80	Cellulose
54	8842.1-2338-54	1	Trace silver foil	<b>None detected</b>	Foil/binder		None detected
		2	Gray/green brittle material with paint and debris	<b>None detected</b>	Filler, Binder, Paint, Debris	2	Cellulose
		3	Brown mastic	<b>None detected</b>	Mastic/binder	3	Cellulose
55	8842.1-2338-55	1	Trace silver foil	<b>None detected</b>	Foil/binder		None detected
		2	Gray/green brittle material with paint and debris	<b>None detected</b>	Filler, Binder, Paint, Debris	2	Cellulose
		3	Brown mastic	<b>None detected</b>	Mastic/binder	2	Cellulose
56	8842.1-2338-56	1	White soft/loose fibrous material with paint	<b>None detected</b>	Filler, Binder, Paint	4	Cellulose
57	8842.1-2338-57	1	White soft/loose fibrous material with paint	<b>None detected</b>	Filler, Binder, Paint	3	Cellulose
		2	Black fibrous material	<b>None detected</b>	Filler, Binder	6	Cellulose
58	8842.1-2338-58	1	Loose gray sandy/brittle material with paint	<b>None detected</b>	Sand, Filler, Binder, Paint	2	Cellulose
59	8842.1-2338-59	1	Loose gray sandy/brittle material with paint	<b>None detected</b>	Sand, Filler, Binder, Paint	3	Cellulose
60	8842.1-2338-60	1	Loose gray sandy/brittle material with paint and debris	<b>None detected</b>	Sand, Filler, Binder, Paint, Debris	4	Cellulose

## SEATTLE ASBESTOS TEST

Lynnwood Laboratory: 19701 Scriber Lake Road, Suite 103, Lynnwood, WA 98036, Tel: 425.673.9850, Fax: 425.673.9810, NVLAP Lab Code: 200768-0


Disclaimer: This report must not be used by the client to claim product certification, approval, or endorsement by Seattle Asbestos Test, LLC, NVLAP, NIST, or any agency of the Federal government.

### ANALYTICAL LABORATORY REPORT PLM by Method EPA/600/R-93/116

Attn.: Anthony Fullerton  
Job#: 8842.1  
Samples Rec'd: 71  
Project Loc.: 2338 11th St, Tacoma, WA

Client: Med-Tox, Northwest  
Batch#: 201911093  
Date Analyzed: 7/3/2019

Address: PO Box 1446, Auburn, WA 98071-1446  
Date Received: 6/27/2019  
Samples Analyzed: 71

Analyzed by:  Yajun Gao

Reviewed by: Steve (Fanyao) Zhang, President 

61	8842.1-2338-61	1	Gray soft/elastic material with paint and debris	None detected	Binder, Filler, Paint, Debris	2	Cellulose
62	8842.1-2338-62	1	Gray soft/elastic material with paint and debris	None detected	Binder, Filler, Paint, Debris	3	Cellulose
63	8842.1-2338-63	1	Silver paint	None detected	Paint, Filler	3	Cellulose
		2	Black asphaltic material	None detected	Asphalt/binder	2	Cellulose
		3	Black asphaltic material with fibrous material	None detected	Asphalt/binder, Filler	26	Glass fibers, Cellulose
		4	Black asphaltic material	None detected	Asphalt/binder	2	Cellulose
		5	Black asphaltic material with fibrous material	None detected	Asphalt/binder, Filler	28	Glass fibers, Cellulose
		6	Black asphaltic material	None detected	Asphalt/binder	2	Cellulose
		7	Black asphaltic material with fibrous material	None detected	Asphalt/binder, Filler	30	Cellulose
		8	Black asphaltic material	None detected	Asphalt/binder	3	Cellulose
		9	Black asphaltic material with fibrous material	None detected	Asphalt/binder, Filler	32	Cellulose
		10	Black asphaltic material	None detected	Asphalt/binder	2	Cellulose
		11	Black asphaltic material with fibrous material	None detected	Asphalt/binder, Filler	30	Cellulose
64	8842.1-2338-64	1	Silver paint	None detected	Paint, Filler	4	Cellulose
		2	Black asphaltic material	None detected	Asphalt/binder	2	Cellulose
		3	Black asphaltic material with fibrous material	None detected	Asphalt/binder, Filler	26	Glass fibers, Cellulose
		4	Black asphaltic material	None detected	Asphalt/binder	3	Cellulose
		5	Black asphaltic material with fibrous material	None detected	Asphalt/binder, Filler	28	Glass fibers, Cellulose
		6	Black asphaltic material	None detected	Asphalt/binder	2	Cellulose
		7	Black asphaltic material with fibrous material	None detected	Asphalt/binder, Filler	60	Glass fibers, Cellulose