



Tested Item Number: 774280	
Tested Unit Ordering Code: LED9A19/P60W/927/J/D/2/1P	
Related Item Number: 774281	
Related Ordering Code: LED9A19/P60W/930/J/D/2/1P	
Related Item Number: 774282	
Related Ordering Code: LED9A19/P60W/940/J/D/2/1P	

	Manufacturer	Product	Model Number	Overall Rating	Lamps per Dimmer		Notes	
					Recommended Minimum	Maximum Tested*		
Incandescent/Halogen (Triac/Phase Cut/Leading Edge Dimmers)	Leviton	a IllumaTech	IPI06	Bad	1	6	Not smooth, doesn't operate well at low levels, flickers while dimming	
		b SureSlide	6633-P	Best	1	6	Dims completely	
		c Vizia	VPI06-1LZ	Good	1	6	Not smooth, slight flicker while operating, dims completely	
	Lutron	d Toggle	TG-600	Best	1	6	Dims to 3%	
		e Lumea	LGCL-600	Best	1	6	Dims to 2%	
		f Diva	DV-600	Good	1	6	Not smooth, slight flicker while operating, dims completely	
		g Skylark	S-600	Best	1	6	Dims completely	
	Legrand	h Maestro	MAW-600	Not Compatible	1	6		
		i Titan	CD703-PW	Bad	3	6	Poor operation <3, not smooth while operating, dims to 3%	
		j Harmony	D703-PTC	Bad	1	6	Poor operation <3, dims completely	
	k Harmony	H703-PTC	Bad	2	6	Not compatible with 1, poor operation with 2		
CFL/LED	Leviton	l IllumaTech	IPL06	Best	1	6	Delay in operation, dims completely	
		m Sureslide	6674	Good	1	6	Delay in operation, HE dead travel (35%), dims completely	
		n Decora	6672	Good	1	6	Delay in operation, HE dead travel (30%), dims to 1%	
	Lutron	o Decora Slide	DSL06-1LZ	Good	1	6	HE dead travel (30%), dims completely	
		p Skylark	CTCL-153	Best	1	6	Dims to 2%	
		q Diva	DVCL-153PL	Best	1	6	Very slight flicker while operating, dims completely	
		r Maestro	MACL-153MLH	Best	1	6	Dims completely	
		s Skylark	SCL-153P	Best	1	6	Dims completely	
		t Toggle	TGCL-153PH	Best	1	6	Dims completely	
		u Radio RA	RA2RR-6CL-PD	Best	1	6	Dims completely	
		v Sunnata Touch	STCL-153M-BL	Best	1	6	Dims completely	
	Legrand	w Harmony	DCL453-PTC	Best	1	6	Dims to 2%	
		x Harmony	HCL453PTC	Best	1	6	Dims to 2%	
		y Adorne Paddle	ADPD453LM2	Good	1	6	HE dead travel (10%), dims completely	
	Electronic Low Voltage	Leviton	y Vizia	VPE04	Best	1	6	Dims completely
			z IllumaTech	IPE04	Not Compatible	1	6	
aa Decora			6615-P	Bad	1	6	HE dead travel (60%), flickers at low levels while operating, dims to 9%	
Lutron		ab Skylark Countour	CTELV-303P	Best	1	6	Dims completely	
		ac Diva	DVELV-300P	Best	1	6	Dims completely	
		ad Maestro	MAELV-600	Best	1	6	Dims completely	
		ae Skylark	SELVB-300P	Best	1	6	Dims completely	
Legrand		af VIERTI	VTCL-600M-W	Best	1	6	Dims completely	
		ag Scene Director	SCELV	Best	1	6	Dims completely	
Magnetic Low Voltage	Leviton	ah Vizia	VPM-06	Good	1	6	Slight flicker while operating, dims completely	
		ai Decora	6613-P	Best	1	6	Dims completely	
	Lutron	aj Maestro	MALV-600	Not Compatible	1	6		
		Legrand	ak Harmony	DLV703-PW	Good	1	6	Not smooth, jumps while dimming, dims completely
	al Titan		CDLV703-PW	Good	1	6	Not smooth, jumps while dimming, dims completely	
Smart Dimmer	Leviton	am Decora Digital (Bluetooth)	DDMX1-BLZ	Best	1	6	Dims to <1%	
		an Decora Smart Z-Wave Technology	DZ6HD	Best	1	6	Dims completely	
		ao Decora Smart WiFi Technology	DW1KD	Best	1	6	Dims completely	
	Lutron	ap Caseta Wireless smart dimmer Wi-Fi	PD-10NXD	Good	1	6	Dims to 6%	
		aq Caseta Wireless smart dimmer Wi-Fi	PD-6WCL	Good	1	6	Dims to 5%	
	GE	ar Z WAVE	ZW3005	Good	1	6	Dims to 5%	
	Eaton	ay Eaton Smart Dimmer		Best	1	6	Dims completely	
Universal	Legrand	as Adorne SoftTap	ADTP703TU	Bad	1	6	Not smooth, flickers while operating, flickers low levels, dims to 8%	
		at Miro Decorator	DRD4-W	Good	1	6	Not smooth, flickers while operating, dims completely	
		au Harmony	H703PTUTC	Not Compatible	1	6		
		av Adorne Whisper	ADWR700MMTUW2	Good	1	6	Flickers at low levels, dims completely	
	Cooper	aw Adorne Touch	ADTH700MMTUM2	Best	1	6	Dims completely	
		ax Decorator	DAL06P-C2-K-L	Best	1	6	Dims completely	
	Eaton	az Universal Toggle Dimmer 120V	TUL06P-C2-KB-L	Good	1	6	Significant delay in operation, dims completely	
		ba Universal Slide Dimmer	FSUL06	Good	1	6	Significant delay in operation, dims completely	
		bb Universal Side Toggle Dimmer	LSO6P	Good	1	6	Significant delay in operation, dims completely	
		bc Universal Slide Toggle Dimmer	LD06P	Good	1	6	Significant delay in operation, dims completely	
		bd Universal Decorator Dimmer	LDL06P-W-2KB-LW	Good	1	6	Significant delay in operation, dims completely	

*Maximum Tested (Lamps per Dimmer) - Additional lamps may work with your dimmer system. For maximum capacity please consult dimmer manufacturer.

†May experience "pop-on", lights cannot be turned on immediately to their minimum level. The slider needs to be raised above the minimum light level for the lights to first turn on if they were initially off. Then, the slider can be lowered to get to a lower light level; the dimmer cannot be turned on to just the minimum level.

Overall Rating	Description
Not Compatible	One or more of the following observed: Major flickering at various points, significant audible noise, no dimming range, does not turn off.
Bad	One or more of the following observed: Some flickering observed at various points, audible noise may be present, dimming not smooth.
Good	One or more of the following observed: Minor flickering at some point may exist. Dead travel may exist, which means there may be periods of time when the slider (or other form of control button) is moved without affecting the light level. These periods of dead travel are minor and most of the time not visible. Minor audible noise.
Best	Most of the following observed: No flickering, minimal audible noise (typically less than 25 dBa), wide dimming range - can dim down to 20% or less of light output.
High End (HE) Dead Travel	Determines how much, if any, dead travel exists at the top and bottom of the dimmer's range. Dead travel is when the slider can be moved without affecting the light level.
Low End (LE) Dead Travel	

©2025 Bulbrite Industries Inc.
All Rights Reserved.