Inspection Report

Report Number: 564971

Report Generated For Customer: Rosa Subirat

Date of Inspection: 5/11/2023

Location of Inspection: Tumwater, WA, 98501

For Questions, call us at (866) 935-2057 or email us at services@lemonsquad.com

Important Disclosures:

This Inspection Report is governed by the terms and conditions of the order which are available at https://lemonsquad.com/terms and which contain important information, disclosures, and disclaimers.

This Inspection Report is for the sole and exclusive use of the Customer named above and may not be used or relied upon by any third party including, without limitation, any purchaser of a vehicle from Customer.

Without limiting the Limited Warranty, Disclaimers, Limitations on Liability and Dispute Resolution provisions of the terms and conditions (available at https://lemonsquad.com/terms), there are no implied or express warranties or guarantees of any kind in connection with any vehicle inspection. The vehicle inspection is intended solely as an "evaluation" of a given vehicle's condition at the time, date and place of examination. Wrench Inc., and its affiliates including LemonSquad, specifically disclaims any liability for any loss or damage arising in connection with ownership or operation of said vehicle and further disclaims any liability of any hidden wreck, flood damage or tampered components not readily apparent upon visual inspection. The items visually inspected were in the reported condition listed in the report at the time of the inspection only. A visual inspection will not identify the working condition of each and every vehicle part or component, nor will a visual inspection identify any or all missing, tampered or altered components. Intermittent component or systems issues or failures may not present themselves at the precise time of inspection and/or a vehicle may be tuned in a manner to mask or minimize any such issues; in either case, such intermittent issues may not be discoverable during inspection. Further disclaimed is any liability for any damage or defects not found during inspection. Other conditions may exist which did not occur or appear during inspection. It is the customer's responsibility to ensure the vehicle to be inspected is in a state in which the vehicle is legal to drive on public roads, safe and functioning well enough to start and drive, and located in a space that is accessible and allows the inspector full access to vehicle components. Vehicles that are not safe, legal, or in a running condition will not have a test drive performed. Inspection reports are for information only and are not to be considered a recommendation for or against the purchase of the inspected vehicle.

Report #564971

1978 Toyota FJ Cruiser



Summary

The vehicle was in the garage when i arrived.

Exterior
Good initial impression. There are some scratches around the body. Some body work has been performed, body lines and gaps are good. The paint condition is fair. The windshield has a crack and will require replacement. The wheels and tires are in good condition. All lights are clear and function normally. No signs of collision. The chassis/frame has been sprayed around the wheel openings. There is some oil seepage from front diff, transfer case, and engine. There is rust in the rear that will need repair. The underside shows areas of surface rust. See pictures.

Interior
The interior is in fair condition showing normal wear. The drivers seat lower is coming apart. The wipers and radio all work as they should. The windshield washer was inoperative.

Mechanical
Under the hood is clean. Some fluids will need service. There are no modifications noted. There are no obvious coolant leaks. There are no signs of collision or repair. There is some oil seepage from the engine.

Road test
The vehicle drove well during test drive. Normal engine power. The transmission shifts smoothly. Brakes are good. The vehicle tracks straight, even under braking. There were no abnormal suspension or steering noises.

Tires/wheels
The vehicle has four High Country brand tires sized 30X9.50R15 installed. All four tires show 7/32 tread depth.

Vehicle Information

Year	1978
Make	Toyota
Model	FJ Cruiser
VIN	FJ40268591
Stock No.	
Mileage	00458
Fuel Type	Gas
Interior Color	Grey
Exterior Color	Red
Interior Material	Vinyl
Transmission	Manual
Drive Type	Four Wheel Drive
Engine Cylinders	6 Cylinder

Road Test

Road Test	Yes
Engine Starting Easily	Good
Engine running well after Started	Good
Transmission performance	Good
Clutch Performance	Good
Differential Performance	Good
Transfer Case Performance	Good
Wheel Bearing Performance	Good
Braking Performance	Good
Suspension Performance	Good
Steering Performance and Alignment	Good

Exterior

Wiper Blades	Good
Windshield Washer	Issues
The windshield washer does not work.	
Body Panel Alignment	Good
Scratches	Issues
There are minor misc scratches around the vehicle. Normal for mileage and most too small to see in photos.	
Paint Condition	Good
Seals	Issues
The body seals around the windows are showing signs of age and wear. This includes the doors, windows, trunk, and other miscellaneous body seals. They will need replacement.	
Rust	Issues
There is rust in the rear around the floor and rear rear door. The underside shows areas of surface rust. See pictures.	
Exterior Lights	Good
Power Door Mirrors	Issues
The door mirror housings are cracked.	
Bumpers	Good
Side Moldings	Good
Underbody/Frame Condition	Good
Glass	Issues
The windshield has a crack and will need to be replaced/repaired.	
Floors	Issues
The floor shows some rust in the rear.	
Rockers	Good
Quarter Panels	Good
Body Filler Used	Issues
I checked the vehicle with a magnet and found it to stick all around but was weaker in the lower panels. Not excessive.	
Hood	Good

Interior

Steering Wheel	Good
Horn	Good
Seat Condition	Issues
Driver seat is coming apart.	
Seat Belts	Good
Radio/Navigation/DVD	Good
Inner Door Panels	Issues
The inner door panels show wear consistent with age and mileage.	
Center Console	Good
Dash	Good
Dash Lights Working	Good
Heater	Good
Floor Mats	Good
Signs of Smoking?	Good
Cup Holders	Good
Headliner	Issues
The headliner shows areas of sagging and will need to be either re-glued or replaced to be fixed.	
Blower Motor	Good
Instrument Cluster/Gauges	Good
Unusual Odors	Good
Window Function	Good
Interior Trim	Issues
The interior trim shows normal wear consistent with age and mileage.	
Sun Visors	Good

Hood	Good
Doors	Good
Dings	Good
Dents	Good

Mechanical

Radiator Cap Sealing Properly	Good
Air Filter	Good
Battery Condition	Good
Coolant Leaks	Good
Charging System	Good
Cooling Fan Condition Mechanical/Electronic	Good
Hoses and Clamps Age/Cracking	Good
Radiator Condition	Good
Engine Coolant Condition	Good
Belts	Good
Power Steering System	Good
Power Steering Fluid Condition	Good
Engine Oil Condition	Good
Engine Oil Leaks	Issues

The engine is seeping some oil from the underside. There were no drips at time of inspection. This area should be cleaned off and rechecked to verify source of leak or leaks.

Transmission Fluid Leaks	Good
Brake System Condition	Good
Brake Fluid Leaks	Good
Transfer Case Leaks	Issues

The transfer case is seeping fluid and should be cleaned off to determine the source of seepage.

Differential leaks	Issues

The front differential is seeping fluid.

Muffler System	Good
CV Boots and Joints	Good
Shocks and bushings Condition. Leaking?	Good
Ball Joints and Tie Rods	Good
Modifications	Good

Tire / Wheels

Manufacturer	
Driver's Front Tire	High Country
Passenger's Front Tire	HIGH COUNTRY
Driver's 1st Axle Outer Tire	HIGH COUNTRY
Passenger's 1st Axle Outer Tire	HIGH COUNTRY
Size	
Driver's Front Tire	30X9/50R15
Passenger's Front Tire	30X9/50R15
Driver's 1st Axle Outer Tire	30X9/50R15
Passenger's 1st Axle Outer Tire	30X9/50R15
Axle Count	
Tire Condition	
Driver's Front Tire	No Issues
Passenger's Front Tire	No Issues
Driver's 1st Axle Outer Tire	No Issues
Passenger's 1st Axle Outer Tire	No Issues
Wheel Condition	
Driver's Front Tire	No Issues
Driver's 1st Axle Outer Tire	No Issues
Passenger's Front Tire	No Issues
Passenger's 1st Axle Outer Tire	No Issues
Tire Tread	
Driver's Front Tire	7/32
Passenger's Front Tire	7/32
Driver's 1st Axle Outer Tire	7/32
Passenger's 1st Axle Outer Tire	7/32
Spare Tire	Yes

Vehicle Images






1
3
5
R


BRAKE
FASTEN BELTS
CHOKE
HAZARD
WIPE WASH
FAN PULL
FRESH PULL
TUNE
5 7 9 12 16
TONE SW VOL
VENT
HEAT
DEF


ADED
ONLY
20
40
60
80
0
100
mph
20
40
60
80
100
120
140
0
km/h
00458
160
L
H
OIL
E
F
FUEL
C
H
TEMP
-30
A
30+
AMP


TOYO






DRIVE












UNLEADED
FUEL ONLY


UNLEADED
FUEL ONLY





RADIAL


WASHINGTON
ABG2580
EVERGREEN STATE
B 580622
2023









































MFD. BY : TOYOTA MOTOR CO.,LTD.
Feb. 1978
GVWR(LBS/KGS): 4885/2215
GAWR(LBS/KGS): FRT. 3065/1390 WITH H78-15(B) TIRES.
15x5½-JJ RIMS, AT32 PSI/220 KPA COLD.
GAWR(LBS/KGS): RR. 3220/1461 WITH H78-15(B) TIRES.
15x5½-JJ RIMS, AT32 PSI/220 KPA COLD.
THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR VEHICLE SAFETY STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.
VEH. IDENT. NO. : FJ40- 268591
VEH. TYPE : MPV










RADIAL A/P
HIGH COUNTRY







6PR. LT
M+S


VEHICLE EMISSION CONTROL INFORMATION
ENGINE FAMILY 2F(F)
EVAP. FAMILY EV-F
257.9 CID
EXHAUST EMISSION CONTROL SYSTEM A.I+EGR
MAKE ALL ADJUSTMENTS WITH ENGINE AT NORMAL OPERATING TEMPERATURE, CHOKE FULL OPEN, AIR CLEANER INSTALLED AND AIR CONDITIONING OFF.
ENGINE TUNE UP SPECIFICATIONS
IDLE SPEED(RPM) 650(N)
IGNITION TIMING(°BTC) 7°@ IDLE
IDLE MIXTURE SETTING (SEE REPAIR MANUAL FOR THE PARTICULARS) LEAN DROP IDLE SET TO THE FOLLOWING VALUE AT BEST IDLE 690 RPM(N) TURN IN IDLE MIXTURE ADJUSTING SCREW UNTIL 650 RPM(N)
FAST IDLE SPEED(RPM) 1,800@ EGR, VACUUM RETARD AND EVAP. PURGE OFF.
VALVE CLEARANCE(IN.) INTAKE 0.008(0.20mm) EXHAUST 0.014(0.35mm)
TOYOTA MOTOR CO., LTD.
NON-CATALYST
THIS VEHICLE CONFORMS TO U.S. EPA REGULATIONS APPLICABLE TO 1978 MODEL YEAR NEW MOTOR VEHICLES.
257.9 cu.in.











HIGH COUNTRY
RADIAL A/P


4 8 B
J 0 7 0 3 5


HIGH COUNTRY
RADIAL A/T



TOYOTA
Land Cruiser
HIGH COUNTRY





CAUTION








IGNITER ASSY
89620-60030
ND 131100-1213
12V
MADE IN JAPAN
21
b
















TOYOT
MODEL FJ40LV-
ENGINE 2F 4230cc/257.9cu.in.
FRAME No. FJ40-266591
COLOR/TRIM 309 LE11 保安基準適合
TRANS./AXLE F42 K082 0-12
PLANT/G.V.W. A11
トヨタ自動車工業株式会社
TOYOTA MOTOR CO.,LTD.
MADE IN JAPAN
60152














AISAN
JAPAN










30X9.50R15 6PR LT
HIGH
M+S




RADIAL A/P
HIGH COUNTRY












POCKET
GEAR SHIFTING INSTRUCTIONS
TRANSMISSION
TRANSFER
LEVER
H₂ (HIGH RANGE AND 4x2) : FOR ON-THE
H₄ (HIGH RANGE AND 4x4) : FOR OFF-THE
: SANDY, SNOWY OR SLIPPERY ROAD.
(FRONT DRIVE WILL BE ENGAGED.)
L₄ (LOW RANGE AND 4x4) : FOR THE MAXIM
TRACTION. (FRONT DRIVE WILL BE
ENGAGED AUTOMATICALLY.)


DISTRIBUTOR CAP
WORLDMARK













TOYOTA
4 WHEEL DRIVE
RADIAL
HIGH COUNTRY






VENT
HEAT
DEF


BRAKE
FASTEN BELTS
CHOKE
HAZARD
WIPE WASH
FAN PULL
FRESH PULL
WARM PULL
TUNE
TONE SW VOL
VENT
HEAT
DEF


1 3
R 2 4


















20
40
60
80
0
100
mph
BRAKE
FASTEN BELTS
CHOKE
LIGHTS
OIL
FUEL
TEMP
AMP
WIPE WASH
FAN PULL


20 40 60 80
0 100
mph
20 40 60 80 100 120 140
0
km/h
004589
160
BRAKE
L H
E F
OIL
FUEL
C H
30 A 30
TEMP
AMP
epco


RADIAL A/P
HIGH COUNTRY
RADIAL A/P
HIGH COUNTRY


RADIAL A/P
HIGH COUNTRY








TOYOTA
WASHINGTON
ABG2580
EVERGREEN STATE


IGLOO


IGLOO





























Scotts
Turf Builder
ULTRAFEED
FAST GREENING | EXTENDED FEEDING
FOR UP TO
3X
LONGER
SECURE
NUTRIENTS


Scotts
TurfBuilder
ULTRAFEED
FAST GREENING | EXTENDED FEEDING
3X LONGER




IGLOO






GTON
10 OCT B 580622
WASHINGTON 2023
G2580
ERGREEN STATE
TOYOTA
4 WHEEL DRIVE


WASHINGTON
10
B
580622
2023
ABG2580
EVERGREEN STATE


DUNLOP
WASH


New Zealand
WASHINGTON
ABG2580
EVERGREEN STATE
TOYOTA
4 WHEEL DRIVE
CHAMPION



Explore maintenance, repair and inspection services here.

https://wrench.com