

45 West Commercial Ave.

Dimmer Compatibility Guide

Product Family Name Item Number: 776787 776788 Ordering Code: Item Number: LED5CA10/27K/FIL/M/3 LED5CA10/30K/FIL/M/3

Ordering Code:

	Manufacturer	Product	Model Number	Overall Rating	Lamps per Dir Recommended Minimum	Maximum Tested*	Notes
	- Wallufacturer	IllumaTech	IPI06	Good	Recommended Minimum 1	6	Dims down to 1%, minor flickering when dimmer is moving
Incandescent/Halogen (Triac/Phase Cut/Leading Edge Dimmers)	Leviton						
		SureSlide	6633-P	Good	1	6	Dims down to 1%, minor flickering when dimmer is movi
		Vizia	VPI06-1LZ	Best	1	6	Dims down to 1%,
	Lutron	Toggler	TG-600	Best	1	6	Dims down to 1%
		Lumea	LGCL-600	Best	1	6	Dims down to 1%
		Diva	DV-600	Best	1	6	Dims down to 1%
		Skylark	S-600	Best	1	6	Dims down to 1%
		Maestro	MAW-600	Good	4	6	Dims down to 1% with 4-6
	Legrand	Titan	CD703-PW	Good	1	6	Dims down to 1%, minor flickering at LE with 1-6
		Harmony	D703-PTC	Good	1	6	Dims down to 1%, minor flickering at LE with 1-6
		Harmony	H703-PTC	Good	1	6	Dims down to 1%, minor flickering at LE with 1-6
	Leviton	IllumaTech	IPL06	Best	1	6	Dims down to 1%
		Sureslide	6674	Best	1	6	Dims down to 1%
		Decora	6672	Best	1	6	Dims down to 1%
		Decora Slide	DSL06-1LZ	Best	1	6	Dims down to 1%
			CTCL-153	Best	1	6	
	Lutron	Skylark					Dims down to 1%
651 (150		Diva	DVCL-153PL	Best	1	6	Dims down to 1%
CFL/LED		Maestro	MACL-153MLH	Best	1	6	Dims down to 1%
		Skylark	SCL-153P	Best	1	6	Dims down to 1%
		Toggler	TGCL-153PH	Best	1	6	Dims down to 1%
		Radio RA	RA2RR-6CL-PD	Best	1	6	Dims down to 1%
	Legrand	Harmony	DCL453-PTC	Good	1	6	Dims down to 1%, minor flickering at LE with 1
		Harmony	HCL453PTC	Good	1	6	Dims down to 1%, minor flickering at LE with 1 - 6
		Adorne Paddle	ADPD453LM2	Best	1	6	Dims down to 1%
			•				•
	Leviton	Vizia	VPE04	Best	1	6	Dims down to 1%
		IllumaTech	IPE04	Best	1	6	Dims down to 1%
		Decora	6615-P	Best	1	6	Dims down to 5%
		Skylark Countour	CTELV-303P	Best	1	6	Dims down to 1%
Electronic Low Voltage	Lutron	Diva	DVELV-300P	Best	1	6	Dims down to 1%
Electronic Low Voltage					1		
		Maestro	MAELV-600	Best		6	Dims down to 1%
		Skylark	SELVB-300P	Best	1	6	Dims down to 1%
		VIERTI	VTEL-600M-W	Best	1	6	Dims down to 1%
	Legrand	Scene Director	SCELV	Best	1	6	Dims down to 1%
Magentic Low Voltage	Leviton	Vizia	VPM-06	Good	2	6	Dims down to 1%
		Decora	6613-P	Best	1	6	Dims down to 1%
	Lutron	Maestro	MALV-600	Not compatible	1	6	Does not turn on with 1-6
		Harmony	DLV703-PW	Best	1	6	Dims down to 1%
	Legrand	Titan	CDLV703-PW	Good	1	6	Dims down to 1%,minor flickering at LE with 1
· ·	0:				-	-	9
	Leviton	Decora Digital (Bluetooth)	DDMX1-BLZ	Best	1	6	Dims down to 1%
Smart Dimmer	Leviton	Decora Smart Z-Wave Technology	DZ6HD	Best	1	6	Dims down to 1%
			DW1KD	Best	1	6	Dims down to 1%
	Leviton	Decora Smart WiFi Technology					
	Lutron	Caseta Wireless smart dimmer Wi-Fi	PD-10NXD	Best	1	6	Dims down to 1%
	Lutron	Caseta Wireless smart dimmer Wi-Fi	PD-6WCL	Best	1	6	Dims down to 1%
	GE	Z WAVE	ZW3005	Best	1	6	Dims down to 1%
	Legrand	Adorne SofTap	ADTP703TU	Best	1	6	Dims down to 1%
		Miro Decorator	DRD4-W	Best	1	6	Dims down to1%
		Harmony	H703PTUTC	Bad	1	6	Dims down to50%
Universal		Adorne Whisper	ADWR700MMTUW2	Best	1	6	Dims down to1%
		Adorne Touch	ADTH700MMTUM2	Best	1	6	Dims down to1%
	Cooper	Decorator	DAL06P-C2-K-L	Best	1	6	Dims down to1%

*Maximum Tested (Lamps per Dimmer) - Additional lamps may work with your dimmer system. For maximum capacity please consult dimmer manufacturer.

†May experience "pop-on", lights cannot be turned on immediately to their minimum level. The slider needs to be raised above the minimum light level for the lights to first turn on if they were initially off. Then, the slider can be lowered to get to a lower light level; the dimmer cannot be turned on to just the minimum level.

Overall Rating					
Not Compatible	One or more of the following observed: Major flickering at various points, significant audible noise, no dimming range, does not turn off.				
Bad	One or more of the following observed: Some flickering observed at various points, audible noise may be present, dimming not smooth.				
	One or more of the following observed: Minor flickering at some point may exist. Dead travel may exist, which means there may be periods of time when the slider (or other form of control button) is moved without affecting the light level. These periods of dead travel are minor and most of the time not visible. Minor audible noise.				
Best	Most of the following observed: No flickering, minimal audible noise (typically less than 25 dBa), wide dimming range - can dim down to 20% or less of light output.				
High End (H.E.) Dead Travel	Determines how much, if any, dead travel exists at the top and bottom of the dimmer's range. Dead travel is when the slider can be moved without affecting the light level.				
Low End (L.E.) Dead Travel	betermines now mount, it airly, dead drawer exists at the top and bottom of the diffinite strange. Dead drawers when the single closed entrous affecting the light level.				

untact Information:
Bulbrite Industries Inc.
1.45 West Commercial Avenue
Moonachie, New Intersy 07074
PYONE: 1.800-528-5555
FAX: 1.800-441-7708
FAX: 1.800-441-7708
AUDIT SHURTER INC.
AUDIT SHURTER INC.
AUDIT SHURTER INC.

II Rights Reserved.