



Tested Unit Item Number: 773286	
Tested Unit Ordering Code: LED12DISC/7/930/J/WHRD/D	

	Manufacturer	Product	Model Number	Overall Rating	Lamps per Dimmer		Notes
					Recommended Minimum	Maximum Tested*	
Incandescent/Halogen (Triac/Phase Cut/Leading Edge Dimmers)	Leviton	a IllumaTech	IPI06	Bad	1	6	Not smooth, abrupt changes, dims to 2%
		b SureSlide	6633-P	Good	1	6	Not smooth, slight flicker while operating, dims completely
		c Vizia	VPI06-1LZ	Good	1	6	Not smooth, slight flicker while operating, dims completely
	Lutron	d Toggle	TG-600	Best	1	6	Dims to 4%
		e Lumea	LGCL-600	Best	1	6	Dims to 2.5%
		f Diva	DV-600	Best	1	6	Dims completely
		g Skylark	S-600	Best	1	6	Dims completely
	Legrand	h Maestro	MAW-600	Not Compatible		6	
		i Titan	CD703-PW	Bad	2	6	Not compatible with 1, poor operation with 2, dims completely
		j Harmony	D703-PTC	Good	1	6	Not smooth, slight flicker at low levels, dims completelyb
k Harmony	H703-PTC	Good	1	6	Poor operation with 1, dims completely		
CFL/LED	Leviton	l IllumaTech	IPL06	Good	1	6	Significant delay in operation, dims completely
		m Sureslide	6674	Good	1	6	Significant delay in operation, HE dead travel (40%), dims completely
		n Decora	6672	Best	1	6	Dims completely
	Lutron	o Decora Slide	DSL06-1LZ	Good	1	6	Not smooth, slight flicker while adjusting, dims completely
		p Skylark	TCCL-153	Good	1	6	Not smooth, slight flicker while adjusting, dims completely
		q Diva	DVCL-153PL	Good	1	6	Not smooth, slight flicker while adjusting, dims completely
		r Maestro	MACL-153MLH	Best	1	6	Dims to 1%
		s Skylark	SCL-153P	Best	1	6	Dims completely
		t Toggle	TGCL-153PH	Best	1	6	Dims completely
		u Radio RA	RA2RR-6CL-PD	Best	1	6	Dims completely
	Legrand	v Sunnata Touch	STCL-153M-BL		1	6	
		w Harmony	DCL453-PTC	Best	1	6	Dims to 4%
		x Harmony	HCL453PTC	Best	1	6	Dims to 4%
x Adorne Paddle	ADPD453LM2	Best	1	6	Dims to 4%		
Electronic Low Voltage	Leviton	y Vizia	VPE04	Best	1	6	Dims completely
		z IllumaTech	IPE04	Not Compatible		6	
	aa Decora	6615-P	Not Compatible		6		
	Lutron	ab Skylark Countour	CTELV-303P	Good	1	6	HE dead travel (60%), dims completely
		ac Diva	DVELV-300P	Good	1	6	HE dead travel (60%), dims completely
		ad Maestro	MAELV-600	Best	1	6	Dims completely
		ae Skylark	SELVB-300P	Good	1	6	HE dead travel (60%), dims completely
	Legrand	af VIERTI	VTEL-600M-W	Good	1	6	HE dead travel (60%), dims completely
ag Scene Director		SCELV	Not Compatible		6		
Magnetic Low Voltage	Leviton	ah Vizia	VPM-06	Good	1	6	Not smooth, flickers while adjusting, dims completely
		ai Decora	6613-P	Good	1	6	Not smooth, flickers while adjusting, dims completely
	Lutron	aj Maestro	MALV-600	Not Compatible		6	
		Legrand	ak Harmony	DLV703-PW	Good	1	6
al Titan	CDLV703-PW		Good	1	6	Not smooth, abrupt changes while adjusting, dims to 2%	
Smart Dimmer	Leviton	am Decora Digital (Bluetooth)	DDMX1-BLZ	Good	1	6	Not smooth, jumps, dims completely
		an Decora Smart Z-Wave Technology	DZ6HD	Best	1	6	Dims completely
		ao Decora Smart WiFi Technology	DW1KD	Best	1	6	Dims completely
	Lutron	ap Caseta Wireless smart dimmer Wi-Fi	PD-10NXD	Good	1	6	Dims to 5%
		aq Caseta Wireless smart dimmer Wi-Fi	PD-6WCL	Good	1	6	Dims to 5%
	GE	ar Z WAVE	ZW3005	Best	1	6	Dims completely
Eaton	av Eaton Smart Dimmer		Best	1	6	Dims completely	
Universal	Legrand	as Adorne SoftTap	ADTP703TU	Not Compatible		6	
		at Miro Decorator	DRD4-W	Best	1	6	Dims completely
		au Harmony	H703PTUTC	Not Compatible		6	
		av Adorne Whisper	ADWR700MMTUM2	Not Compatible		6	Dims completely
	Cooper	aw Adorne Touch	ADTH700MTUM2	Best	1	6	Dims completely
		ax Decorator	DAL06P-C2-K-L	Good	1	6	Not smooth, slight flicker while adjusting, dims completely
	Eaton	az Universal Toggle Dimmer 120V	TUL06P-C2-KB-L	Good	1	6	Significant delay in operation, dims completely
		ba Universal Side Dimmer	FSUL06	Good	1	6	Significant delay in operation, dims completely
		bb Universal Side Toggle Dimmer	LS06P	Good	1	6	Significant delay in operation, dims completely
		bc Universal Side Toggle Dimmer	LD06P	Good	1	6	Significant delay in operation, dims completely
bd Universal Decorator Dimmer	DUL06P-W-2KB-LW	Good	1	6	Significant delay in operation, dims completely		

*Maximum Tested (Lamps per Dimmer) - Additional lamps may work with your dimmer system. For maximum capacity please consult dimmer manufacturer.
†May experience "pop-on", lights cannot be turned on immediately to their minimum level. The slider needs to be raised above the minimum light level for the lights to first turn on if they were initially off. Then, the slider can be lowered to get to a lower light level; the dimmer cannot be turned on to just the minimum level.

Overall Rating	Description
Not Compatible	One or more of the following observed: Major flickering at various points, significant audible noise, no dimming range, does not turn off.
Bad	One or more of the following observed: Some flickering observed at various points, audible noise may be present, dimming not smooth.
Good	One or more of the following observed: Minor flickering at some point may exist. Dead travel may exist, which means there may be periods of time when the slider (or other form of control button) is moved without affecting the light level. These periods of dead travel are minor and most of the time not visible. Minor audible noise.
Best	Most of the following observed: No flickering, minimal audible noise (typically less than 25 dBA), wide dimming range - can dim down to 20% or less of light output.
High End (HE) Dead Travel Low End (LE) Dead Travel	Determines how much, if any, dead travel exists at the top and bottom of the dimmer's range. Dead travel is when the slider can be moved without affecting the light level.

©2025 Bulbrite Industries Inc.
All Rights Reserved.