



Tested Unit Item Number: 776960	
Tested Unit Ordering Code: LED14A19/50K/FIL/3	
Related Item Number: 776961	
Related Ordering Code: LED14A19/50K/FIL/M/3	

	Manufacturer	Product	Model Number	Overall Rating	Lamps per Dimmer		Notes
					Recommended Minimum	Maximum Tested*	
Incandescent/Halogen (Triac/Phase Cut/Leading Edge Dimmers)	Leviton	a IllumaTech	IPI06	Good	1	6	Not smooth, dims to 10%, minor buzzing while dimming
		b SureSlide	6633-P	Good	1	6	Dims to 10%, minor buzzing while dimming
		c Vizia	VPI06-1LZ	Bad	3	6	Flickers below MAX <3, not smooth, dims to 10%, minor buzzing while dimming
	Lutron	d Toggle	TG-600	Good	1	6	Not smooth, dims to 8%, minor buzzing while dimming
		e Lumea	LGLCL-600	Good	1	6	Dims to 7%, minor buzzing while dimming
		f Diva	DV-600	Good	1	6	Dims to <1%, minor buzzing while dimming
		g Skylark	S-600	Good	1	6	Dims to 1%, minor buzzing while dimming
	Legrand	h Maestro	MAW-600	Bad	1	6	Not compatible with 1, minor buzzing while dimming
		i Titan	CD703-PW	Good	1	6	Dims to 15%, minor buzzing while dimming
		j Harmony	D703-PTC	Good	1	6	Minor buzzing while dimming
	k Harmony	H703-PTC	Good	1	6	Dims to 4%, minor buzzing while dimming	
CFL/LED	Leviton	l IllumaTech	IPL06	Good	1	6	Delay in operation, minor buzzing while dimming
		m Sureslide	6674	Good	1	6	Dims to 8%, minor buzzing while dimming
		n Decora	6672	Good	1	6	Minor buzzing while dimming
	Lutron	o Decora Slide	DSL06-1LZ	Bad	1	6	Delay in operation, not smooth, minor buzzing while dimming
		p Skylark	CTCL-153	Not Compatible	1	6	Dims to 20%, minor buzzing while dimming
		q Diva	DVCL-153PL	Good	1	6	Not smooth, slight flicker while dimming, minor buzzing while dimming
		r Maestro	MACL-153MLH	Not Compatible	1	6	Dims to 22%, minor buzzing while dimming
		s Skylark	SCL-153P	Not Compatible	1	6	Dims to 25%, minor buzzing while dimming
		t Toggle	TGCL-153PH	Bad	1	6	Dims to 18%, minor buzzing while dimming
		u Radio RA	RA2RR-6CL-PD	Best	1	6	Dims to 4%, extremely faint buzzing while dimming
		v Harmony	DCL453-PTC	Not Compatible	1	6	Dims to 22%, minor buzzing while dimming
	Legrand	w Harmony	HCL453PTC	Bad	1	6	Dims to 18%, minor buzzing while dimming
		x Adorne Paddle	ADPD453LM2	Not Compatible	1	6	Dims to 26%, minor buzzing while dimming
Electronic Low Voltage	Leviton	y Vizia	VPE04	Best	1	6	Dims to 5%, very faint buzzing while dimming
		z IllumaTech	IPE04	Bad	1	6	Not smooth, dims to 5%, minor buzzing while dimming
	Lutron	aa Decora	6615-P	Bad	1	6	HE dead travel (45%), not smooth, minor buzzing while dimming
		ab Skylark Countour	CTELV-303P	Best	1	6	Dims to 4%, very minor buzzing while dimming
		ac Diva	DVELV-300P	Best	1	6	Dims to 4%, very minor buzzing while dimming
		ad Maestro	MAELV-600	Best	1	6	Dims to 4%, very minor buzzing while dimming
		ae Skylark	SELVB-300P	Best	1	6	Dims to 4%, very minor buzzing while dimming
		af VIERTI	VTEL-600M-W	Best	1	6	Dims to 4%, very minor buzzing while dimming
	Legrand	ag Scene Director	SCELV	Best	1	6	Dims to 4%
Magnetic Low Voltage	Leviton	ah Vizia	VPM-06	Bad	1	6	Dims to 11%, not smooth, minor buzzing while dimming
		ai Decora	6613-P	Bad	1	6	Dims to 4%, minor buzzing while dimming
	Lutron	aj Maestro	MALV-600	Not Compatible	1	6	
		ak Harmony	DLV703-PW	Good	1	6	minor buzzing while dimming
		Legrand	al Titan	CDLV703-PW	Good	1	6
Smart Dimmer	Leviton	am Decora Digital (Bluetooth)	DDMX1-BLZ	Good	1	6	Dims to 8%, minor buzzing while dimming
	Leviton	an Decora Smart Z-Wave Technology	DZ6HD	Not Compatible	1	6	Dims to 30%, minor buzzing while dimming
	Leviton	ao Decora Smart WiFi Technology	DW1KD	Not Compatible	1	6	
	Lutron	ap Caseta Wireless smart dimmer Wi-Fi	PD-10NXD	Good	1	6	Dims to 3%, not smooth, minor buzzing while dimming
	Lutron	aq Caseta Wireless smart dimmer Wi-Fi	PD-6WCL	Not Compatible	1	6	Dims to 30%, minor buzzing while dimming
	GE	ar Z WAVE	ZW3005	Bad	1	6	Not smooth, slight flicker while dimming, minor buzzing while dimming
	Universal	Legrand	as Adorne SoftTap	ADTP703TU	Not Compatible	1	6
at Miro Decorator			DRD4-W	Not Compatible	1	6	
au Harmony			H703PTUTC	Not Compatible	1	6	
av Adorne Whisper			ADWR700MMTUW2	Best	1	6	Very minor buzzing while dimming
aw Adorne Touch			ADTH700MMTUM2	Best	1	6	Very minor buzzing while dimming
Cooper		ax Decorator	DAL06P-C2-K-L	Good	1	6	Dims to 2%, minor buzzing while dimming
		ay Skye	SAL06P-W-K-L	Good	1	6	

*Maximum Tested (Lamps per Dimmer) - Additional lamps may work with your dimmer system. For maximum capacity please consult dimmer manufacturer.

†May experience "pop-on", lights cannot be turned on immediately to their minimum level. The slider needs to be raised above the minimum light level for the lights to first turn on if they were initially off. Then, the slider can be lowered to get to a lower light level; the dimmer cannot be turned on to just the minimum level.

Overall Rating	Description
Not Compatible	One or more of the following observed: Major flickering at various points, significant audible noise, no dimming range, does not turn off.
Bad	One or more of the following observed: Some flickering observed at various points, audible noise may be present, dimming not smooth.
Good	One or more of the following observed: Minor flickering at some point may exist. Dead travel may exist, which means there may be periods of time when the slider (or other form of control button) is moved without affecting the light level. These periods of dead travel are minor and most of the time not visible. Minor audible noise.
Best	Most of the following observed: No flickering, minimal audible noise (typically less than 25 dBA), wide dimming range - can dim down to 20% or less of light output.
High End (HE) Dead Travel Low End (LE) Dead Travel	Determines how much, if any, dead travel exists at the top and bottom of the dimmer's range. Dead travel is when the slider can be moved without affecting the light level.

©2025 Bulbrite Industries Inc.

All Rights Reserved.