

Tested Unit Item Number:	772860
Tested Unit Ordering Code:	LED15BR40/827/D/5
Related Item Number:	772861
Related Ordering Code:	LED15BR40/830/D/5

	Manufacturer	Product	Model Number	Overall Rating	Lamps per Dimmer		Notes
					Recommended Minimum	Maximum Tested*	
Incandescent/Halogen (Triac/Phase Cut/Leading Edge Dimmers)	Leviton	a IllumaTech	IPI06	Good	1	6	Slight flicker at low levels, not smooth, dims completely
		b SureSlide	6633-P	Good	1	6	Slight flicker at low levels, dims completely
		c Vizia	VPI06-1LZ	Good	1	6	Not smooth, flickers while operating, dims completely
	Lutron	d Toggler	TG-600	Good	1	6	Inconsistent dimming, dims to <1%
		e Lumina	LGCL-600	Best	1	6	Dims completely
		f Diva	DV-600	Best	1	6	Dims completely
		g Skylark	S-600	Best	1	6	Dims completely
		h Maestro	MAW-600	Not Compatible		6	
	Legrand	i Titan	CD703-PW	Not Compatible	3	6	Not compatible <3, not smooth 3 or more, dims completely
		j Harmony	D703-PTC	Not Compatible	3	6	Not compatible <3, not smooth 3 or more, dims completely
		k Harmony	H703-PTC	Not Compatible	3	6	not compatible <3, poor operation 3 or more, dims completely
CFL/LED	Leviton	l IllumaTech	IPL06	Good	1	6	Delay in operation, not smooth, flickers during operation, dims completely
		m Sureslide	6674	Bad	1	6	Delay in operation, HE dead travel (30%), flicker during operation, dims completely
		n Decora	6672	Good	1	6	Not smooth, flickers while operating, dims completely
	Lutron	o Decora Slide	DSL06-1LZ	Bad	1	6	Flickers during operation, not smooth, dims completely
		p Skylark	CTCL-153	Best	1	6	Dims completely
		q Diva	DVCL-153PL	Best	1	6	Dims completely
		r Maestro	MACL-153MLH	Best	1	6	Dims completely
		s Skylark	SCL-153P	Best	1	6	Dims completely
		t Toggler	TGCL-153PH	Best	1	6	Dims completely
		u Radio RA	RA2RR-6CL-PD	Good	1	6	Not smooth, slight flicker while operating, dims completely
	Legrand	v Sunnata Touch	STCL-153M-BL		1	6	
		w Harmony	DCL453-PTC	Best	1	6	Dims <1%
		x Harmony	HCL453PTC	Best	1	6	Dims completely
		y Adorne Paddle	ADPD453LM2	Best	1	6	Dims to 1%
Electronic Low Voltage	Leviton	y Vizia	VPE04	Bad	1	6	Not smooth, flickers during operation, dims to 1%
		z IllumaTech	IPE04	Not Compatible		6	
	Lutron	aa Decora	6615-P	Bad	1	6	Not smooth, flickers during operation, flickers at low levels, dims to 8%
		ab Skylark Countour	CTELV-303P	Best	1	6	Dims completely
		ac Diva	DVELV-300P	Best	1	6	Dims completely
		ad Maestro	MAELV-600	Best	1	6	Dims completely
		ae Skylark	SELVB-300P	Best	1	6	Dims completely
		af VIERTI	VTEL-600M-W	Best	1	6	Dims completely
Magnetic Low Voltage	Leviton	ah Vizia	VPM-06	Good	1	6	Not smooth, flickers while operating, dims completely
		ai Decora	6613-P	Best	1	6	Dims completely
	Lutron	aj Maestro	MALV-600	Not Compatible		6	
		ak Harmony	DLV703-PW	Bad	1	6	Not smooth, operates inconsistently, dims completely
	Legrand	al Titan	CDLV703-PW	Bad	2	6	Not compatible with 1, dims completely
Smart Dimmer	Leviton	am Decora Digital (Bluetooth)	DDMX1-BLZ	Bad	1	6	Not smooth, inconsistent, jumps and flickers while dimming, dims completely
		an Decora Smart Z-Wave Technology	DZ6HD	Best	1	6	Dims completely
		ao Decora Smart WiFi Technology	DW1KD	Best	1	6	Dims completely
	Lutron	ap Caseta Wireless smart dimmer Wi-Fi	PD-10NXD	Best	1	6	Dims to 4%
		aq Caseta Wireless smart dimmer Wi-Fi	PD-6WCL	Bad	1	6	Not smooth, flickers and jumps during operation, dims completely
	GE	ar Z WAVE	ZW3005	Bad	1	6	Not smooth, flickers and jumps during operation, dims completely
	Eaton	ay Eaton Smart Dimmer		Best	1	6	Dims completely
Universal	Legrand	as Adorne SoftTap	ADTP703TU	Not Compatible	3	6	Not compatible <3, not smooth with 3 or more, dims to <1%
		at Miro Decorator	DRD4-W	Good	1	6	Not smooth, flickers at high levels, inconsistent, dims completely
		au Harmony	H703PTUTC	Not Compatible	3	6	Not compatible <3
		av Adorne Whisper	ADWR700MMTUW2	Good	1	6	Not smooth, flickers at various points, inconsistent, dims completely
		aw Adorne Touch	ADTH700MMTUW2	Good	1	6	Not smooth, flickers and jumps, dims completely
	Cooper	ax Decorator	DAL06P-C2-K-L	Good	1	6	Slight flicker at low levels, not smooth, dims completely
		ay Universal Toggle Dimmer 120V	TUL06P-C2-KB-L	Bad	1	6	Delay in operation, not smooth, flickers during operation, dims completely
	Eaton	ba Universal Slide Dimmer	FSUL06	Good	1	6	Delay in operation, flickers at low levels, dims to 1%
		bb Universal Slide Toggle Dimmer	LSO6P	Good	1	6	Delay in operation, flickers at low levels, dims to 1%
		bc Universal Slide Toggle Dimmer	LD06P	Bad	1	6	Delay in operation, not smooth, flickers during operation, dims completely
		bd Universal Decorator Dimmer	DUL06P-W-2KB-LW	Good	1	6	Delay in operation, flickers at low levels, dims to 1%

*Maximum Tested (Lamps per Dimmer) - Additional lamps may work with your dimmer system. For maximum capacity please consult dimmer manufacturer.
†May experience "pop-on", lights cannot be turned on immediately to their minimum level. The slider needs to be raised above the minimum light level for the lights to first turn on if they were initially off. Then, the slider can be lowered to get to a lower light level; the dimmer cannot be turned on to just the minimum level.

Overall Rating	Description
Not Compatible	One or more of the following observed: Major flickering at various points, significant audible noise, no dimming range, does not turn off.
Bad	One or more of the following observed: Some flickering observed at various points, audible noise may be present, dimming not smooth.
Good	One or more of the following observed: Minor flickering at some point may exist. Dead travel may exist, which means there may be periods of time when the slider (or other form of control button) is moved without affecting the light level. These periods of dead travel are minor and most of the time not visible. Minor audible noise.
Best	Most of the following observed: No flickering, minimal audible noise (typically less than 25 dBA), wide dimming range - can dim down to 20% or less of light output.
High End (HE) Dead Travel Low End (LE) Dead Travel	Determines how much, if any, dead travel exists at the top and bottom of the dimmer's range. Dead travel is when the slider can be moved without affecting the light level.