

Dimmer Compatibility Guide

Tested Unit Item Number: 776593
Tested Unit Ordering Code: LED4C15/21K/FIL/SPUN/AMB
Related Item Number: 776592
Related Ordering Code: LED4C15/27K/FIL/SPUN/SAT

				Model Number		Lamps per Dimmer		
	Manufacturer		Product		Overall Rating	Recommended	Maximum	Notes
						Minimum	Tested*	
		а	IllumaTech	IPI06	Good	1	6	Not smooth, flickers while dimming
Incandescent/Halogen (Triac/Phase Cut/Leading Edge Dimmers)	Leviton	ь	SureSlide	6633-P	Not Compatible		6	, <u>, , , , , , , , , , , , , , , , , , </u>
			Vizia	VPI06-1LZ	Good	1	6	Flickers at MAX, 95% at MAX with 1
	Lutron		Toggler	TG-600	Best	1	6	Dims to 2%
			Lumea	LGCL-600	Bad	4	6	75% at MAX with 1, 80% at MAX with 2 or 3, dims completely
			Diva	DV-600	Good	1	6	Slight flicker when dimming, dims completely
			Skylark	S-600	Good	1	6	Slight flicker when dimming, dims completely
			Maestro	MAW-600	Not Compatible	1	6	
	Legrand		Harmony	CD703-PW D703-PTC	Bad Bad	1	6	Not smooth, flickers while dimming, step dims, dims completely Not compatible with 1, flickers while dimming with more than 1, dims completely
			Harmony	H703-PTC	Good	1	6	Slight flicker while dimming, dims completely
		K	Harmony	H703-PTC	G000		6	Slight hicker while dimining, dims completely
	Leviton		IllumaTech	IPL06	Best	1	6	Dims completely
			Sureslide	6674	Best	1	6	Dims completely
			Decora	6672	Best	1	6	Dims completely
			Decora Slide	DSL06-1LZ	Good	1	6	Slight flicker at low levels, dims completely
	Lutron		Skylark	CTCL-153	Good	1	6	LE dead travel, dims to 2 %
CEL (LED			Diva	DVCL-153PL	Best	1	6	Dims completely
CFL/LED			Maestro	MACL-153MLH	Best	1	6	Dims completely
			Skylark	SCL-153P TGCL-153PH	Best Best	1	6	Dims completely Dims completely
			Toggler Radio RA	RA2RR-6CL-PD	Best	1	6	Dims completely
	Legrand		Harmony	DCL453-PTC	Good	1	6	Slight flicker at low levels, dims completely
			Harmony	HCL453PTC	Good	1	6	90% at MAX with 1, flicker while dimming, dims to 3%
			Adorne Paddle	ADPD453LM2	Best	1	6	Dims completely
				•				
Electronic Low Voltage	Leviton		Vizia IllumaTech	VPE04 IPE04	Best	1	6	Dims completely
			Decora	6615-P	Not Compatible Good	1	6	Flickers periodically, flickers while dimming, dims to 9%
			Skylark Countour	CTELV-303P	Good	1	6	HE dead travel (30%), slight flicker while dimming, dims complet
	Lutron		Diva	DVELV-300P	Good	1	6	HE dead travel (30%), slight flicker while dimming, dims complete
			Maestro	MAELV-600	Best	1	6	Dims completely
			Skylark	SELVB-300P	Best	1	6	Dims completely
		at	r VIÉRTI	VTEL-600M-W	Best	1	6	Dims completely
	Legrand	ag	Scene Director	SCELV	Not Compatible		6	. ,
						,		
Magnetic Low Voltage	Leviton		Vizia	VPM-06	Best	1	6	Very slight flicker while dimming, dims completely
			Decora	6613-P	Not Compatible		6	
	Lutron		Maestro	MALV-600	Not Compatible		6	
	Legrand		Harmony	DLV703-PW	Good	1	6	Very slight flicker while dimming, 90% at MAX with 1, dims complete
		al	Titan	CDLV703-PW	Good	1	6	Flickers while dimming, LE dead travel (35%), dims completely
Smart Dimmer	Leviton	an	Decora Digital (Bluetooth)	DDMX1-BLZ	Good	1	6	Slight flicker when dimming, dims completely
	Leviton		Decora Smart Z-Wave Technology	DZ6HD	Best	1	6	Dims completely
	Leviton		Decora Smart WiFi Technology	DW1KD	Best	1	6	Dims completely
	Lutron		Caseta Wireless smart dimmer Wi-Fi	PD-10NXD	Best	1	6	Dims to 4%
	Lutron	_	Caseta Wireless smart dimmer Wi-Fi	PD-6WCL	Best	1	6	Dims completely
		_				1		
	GE	aı	Z WAVE	ZW3005	Good	1	6	Not smooth, flickers while dimming, dims completely
Universal	Legrand	89	Adorne SofTap	ADTP703TU	Not Compatible		6	
		at	Miro Decorator	DRD4-W	Good	1	6	Flickers at various levels, dims completely
			Harmony	H703PTUTC	Not Compatible	1	6	, ,
			Adorne Whisper	ADWR700MMTUW2	Best		6	Dims completely
		av	Adorne Touch	ADTH700MMTUM2	Best	1	6	Dims to 4%
	Cooper	a	Decorator	DAL06P-C2-K-L	Not Compatible		6	
		ay	Skye	SAL06P-W-K-L		1	6	
			1 /					

*Maximum Tested (Lamps per Dimmer) - Additional lamps may work with your dimmer system. For maximum capacity please consult dimmer manufacturer.
†May experience "pop-on", lights cannot be turned on immediately to their minimum level. The slider needs to be raised above the minimum light level for the lights to first turn on if they were initially off. Then, the slider can be lowered to get to a lower light level; the dimmer cannot be turned on to just the minimum level.

Description							
One or more of the following observed: Major flickering at various points, significant audible noise, no dimming range, does not turn off.							
One or more of the following observed: Some flickering observed at various points, audible noise may be present, dimming not smooth.							
One or more of the following observed: Minor flickering at some point may exist. Dead travel may exist, which means there may be periods of time when the slider (or other form of control button) is moved without affecting the light level. These periods of dead travel are minor and most of the time not visible. Minor audible noise.							
Most of the following observed: No flickering, minimal audible noise (typically less than 25 dBa), wide dimming range - can dim down to 20% or less of light output.							
Determines how much, if any, dead travel exists at the top and bottom of the dimmer's range. Dead travel is when the slider can be moved without affecting the light level.							

©2025 Bulbrite Industries Inc.