

Declaration of Conformity In Accordance With ANSI/ASSP Z359.7-2019

Pure Safety Group, Inc. 607 East Sam Houston Pkwy S Suite 800, Pasadena, TX 77053

| Declaration No. | |
|--|---------------------|
| | |
| 2025090901231D | |
| | 7 |
| Manufacturer Name and Address: | |
| 10, 42, 56, 36, 76, 70, 56, 30, 30, 56, 34, 90, 56, 3 | |
| Guardian Fall, 607 East Sam Houston Pkwy S. Suite 800, Pasadena, TX 77503 | |
| | .Q-`_ |
| Product information (name, model number, part number or other information as applicable: | |
| 6' double leg shock absorbing lanyard with HS rebar hooks, HS snap hook, 01231 | |
| Sub SKU(s): 01214, 01215, 01216, 01217, 01218, 01220, 01221, 01222, 01230, 01289, 99-03-0001, 99-03-0005, L321601, L521601 | L421601, |
| | |
| Manufacturer declares that the product listed above is in conformity with the requirements of the following standard(| s): |
| ANSI/ASSP Z359.13-2013 | |
| ANSI/ASSP 2359.13-2013 | 48 / |
| ISO 17025-accredited test laboratory address and contact information: | |
| So 17025 decreated test laboratory address and contact information. | |
| Guardian Fall, 607 East Sam Houston Pkwy S. Suite 800, Pasadena, TX 77503 | $P \in \mathcal{G}$ |
| | 12 |
| Test report reference (title, number, date): | |
| | . VO. |
| Test 101 (3/21/2024, 3/27/2024, 3/28/2024, 4/01/2024) | |
| | |
| | |
| | |
| | |
| | |
| Please contact quality@guardianfall.com for signed report. | |
| ricase contact quality@guardiaman.com for signed report. | |
| | |
| | |