

Figure 9 – 3502 Lincoln Avenue Building Demolition Exterior Photograph




Figure 10 – 3502 Lincoln Avenue Building Demolition Interior Photograph




Figure 11 – 3502 Lincoln Avenue Building Demolition Exterior Photograph



Figure 12 – 3502 Lincoln Avenue Building Demolition Interior Photograph




Figure 13 – 3502 Lincoln Avenue Building Demolition Interior Photograph





Figure 14 – 3502 Lincoln Avenue Building Demolition Interior Photograph



**Figure 15 – 3502 Lincoln Avenue Building Demolition Interior Photograph**




Figure 16 – 3502 Lincoln Avenue Building Demolition Interior Photograph




Figure 17 – 3502 Lincoln Avenue Building Demolition Interior Photograph




Figure 18 – 3502 Lincoln Avenue Building Demolition Interior Photograph



Figure 19 – 3502 Lincoln Avenue Building Demolition Plan View

